

APPENDIX G

LISTED PROPERTIES DOCUMENTATION

Appendix G –

Listed Site Database Search Results for East Waterway Associated Drainage Basins

Introduction:

Sites listed in federal and state environmental databases were queried to provide supplemental information potentially useful during source tracing activities within the East Waterway (EW) watersheds. The database queries were conducted by Environmental Data Resources in December 2009. The database information is not necessary to characterize current stormwater or combined sewer overflow (CSO) discharges to the EW, because these discharges have been characterized directly, including any potential contributions from cleanup sites located within the storm drain (SD) or CSO basins.

Text References:

This appendix was referenced in the following sections of the *East Waterway Operable Unit Revised Draft Supplemental Remedial Investigation Report – Section 9: Source and Pathway Characterization*:

- Section 9.3.6.1 – Ecology Toxics Cleanup Program
- Section 9.4.4.3 – Groundwater Pathway and Inland Cleanup Sites

Map Reference:

This appendix was referenced in the following map of the *East Waterway Operable Unit Revised Draft Supplemental Remedial Investigation Report – Section 9: Source and Pathway Characterization*:

- Map 9-7 – Listed Sites within EW Combined Sewer and Inland Storm Drainage Basins

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
1	UNOCAL #5919	100 BROADWAY	ICR	NA	NR	Lander and Hanford CS	Tank cleanup reported 2-9-99.
3	SEATTLE UNIVERSITY UST 433797, 'PARKING GARAGE	1001 E JAMES WAY	ICR, LUST, and UST	NA	NR	Lander and Hanford CS	Detailed LUST data not listed ("not reported").
4	SEATTLE FIRE STATION 6	101 23RD AVE S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	Petroleum Product LUST impacted soil and was reported 2-28-2000. Independent Cleanup report documented.
5	TURNER BEATTER PROPERTY	109 12TH AVE	Brownfield Site List, CSCSL	Non-halogenated, halogenated organics	Soil and Groundwater	Lander and Hanford CS	Confirmed groundwater and soil non-halogenated, halogenated organic compound and petroleum product impacts.
6	LLOYDS ROCKET & HEATING OIL CO	110 BOREN AVE S	Brownfield Site Listing, CERCLIS (NFA), CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	Petroleum product LUST (8-18-1997) and Confirmed petroleum impacted soil and groundwater reported (4-24-2005).
7	CROWLEY MARINE SERVICES INC	1100 SW MASSACHUSETTS ST	PCB Activity Database	PCBs	NA	Lander and Hanford CS	Listed on PCB Activity Database
9	C MILLER PROPERTY	111 12TH AVE	Brownfield Site Listing, VCP, and CSCSL	Non-halogenated, halogenated organics and Petroleum	Soil and Groundwater	Lander and Hanford CS	Confirmed Petroleum, non-halogenated and halogenated solvents impacting soil and groundwater 7-5-2005.
13	FORMER NU WAY CLEANERS	113 - 12TH AVENUE	Brownfield Site Listing (2), CSCSL	Petroleum and Solvents	Soil and Groundwater	Lander and Hanford CS	Petroleum and Solvent soil and groundwater impacts at this former dry-cleaning site. Three USTs on property.
14	HOSPITAL CORP OF AMERICA 1140, 'SHEPARD AMBULANCE	1140 12TH AVE	Brownfield Site Listing, CSCSL (NFA)	Petroleum and Solvents	Soil and Groundwater	Lander and Hanford CS	Petroleum Spill impacting soil and groundwater Final Cleanup report 8-7-1995. No volume reported.
16	DYNACARE BEACON HILL LAB, 'PACIFIC MEDICAL CTR, 'WA UW PACIFIC MEDICAL CENTER	1200 12TH AVE S	FIFRA / TSCA Tracking System, Brownsfield listing, CSCSL	Petroleum	Soil impacted	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, interim cleanup report received 6-22-93.
17	GULL #0270	1201 E. MADISON	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	Petroleum Product spill impacting soil and groundwater Final cleanup report 10-7-1991.
18	TD AUTO BODY & REPAIR	1209 E FIR ST	CSCSL	Petroleum, metals, Non-halogenated and	Soil, Groundwater, and Sediment	Lander and Hanford CS	Confirmed soil, surface and suspected sediment impacts from petroleum, metals, non-halogenated solvents and halogenated organic compounds and conventional contaminants. 9-8-1994
19	SWEDISH HOSPITAL PHYSICAL THERAPY PARKING LOT	1211 MARION ST.	ICR	Petroleum	Soil	Lander and Hanford CS	10 independent cleanup reports for Petroleum product soil impacts from 1993 to 1995.
21	GARDNER BUILDING	12TH AVE. / E SPRING ST.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	Petroleum Spill impacting soil and groundwater Final Cleanup report 9-29-200. No volume reported.
22	SEATTLE UNIVERSITY LAW SCHOOL	12TH AVE. S. / E.	ICR	Petroleum	Soil	Lander and Hanford CS	Petroleum product spill impacting soil Final Cleanup Report
23	GATZERT ELEMENTARY SCHOOL	1301 E. YESLER WAY	ICIS Integrated Compliance Information System	NA	NR	Lander and Hanford CS	No detail provided
24	QWEST CORPORATION W00291	1313 E COLUMBIA	VCP, CSCSL, LUST, and UST	Petroleum and Arsenic	Soil and Groundwater	Lander and Hanford CS	CSCSL: Groundwater (confirmed) contaminated by petroleum products (confirmed), arsenic code (confirmed), metals - other non-priority pollutant metals (below cleanup level) on 10-12-07. Soil (below cleanup level) contaminated by petroleum products (below cleanup level), arsenic code (below cleanup level), EPA priority pollutants - metals and cyanide (below cleanup level), metals - other non-priority pollutant metals (below cleanup level) on 1-12-07 LUST - affecting groundwater

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
26	TEXACO DOWNSTREAM 211558, 'WA DOT BRADNER PLACE APTS, 'WDOT BRADNER PLACE APARTMENTS	1366 31ST AVE S	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL: soil and groundwater (both confirmed) both contaminated by petroleum products (confirmed); both entered on 3-7-05. 2 VCPs in progress 2 - LUST #1: Groundwater contaminated, cleanup started, release status date 5-21-95. LUST #2: Groundwater contaminated, monitoring, release status date 7-25-96. LUST #3: Soil contaminated, cleanup started, release status date 5-21-95. LUST #4: Soil contaminated, monitoring, release status date 7-25-96 3 - ICR #1: Soil contaminated by petroleum products, interim cleanup report received 8-7-98. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 7-16-98. ICR #3: Soil contaminated by petroleum products, interim cleanup report received 4-14-98. ICR #4: Soil contaminated by petroleum products, interim cleanup report received 1-22-99. ICR #5: Soil and groundwater contaminated by petroleum products, interim cleanup report received 11-13-98. ICR #6: Soil contaminated by petroleum products, interim cleanup report received 3-29-99. ICR #7: Soil contaminated by petroleum products, interim cleanup report received 10-4-99. ICR #8: Soil contaminated by petroleum products, interim cleanup report (Monitoring - May 2000) received 8-7-00. ICR #9: Soil contaminated by petroleum products, interim cleanup report (Monitoring - May 2000) received 8-7-00. ICR #10: Soil contaminated by petroleum products, interim cleanup report received 6-15-00. ICR #11: Soil contaminated by petroleum products, interim cleanup report received 1-17-00. ICR #12: Soil, groundwater and air contaminated by total petroleum hydrocarbons, non-halogenated organic compounds, interim cleanup report received 3-7-94. ICR #13: Unknown contaminated by petroleum products, interim cleanup report received 2-5-96. ICR #14: Groundwater and soil contaminated by petroleum products, interim cleanup report received 9-25-95. ICR #15: Soil contaminated by petroleum products, interim cleanup report received 7-11-96. ICR #16: Soil contaminated by petroleum products, interim cleanup report (Monitoring - November 2000) received 1-12-01. ICR #17: Soil and groundwater contaminated by petroleum products, interim cleanup report (Sampling - August 2001) received 12-4-01. ICR #18: Soil contaminated by petroleum products, interim cleanup report (Quarterly Monitoring - February 2001) received 5-11-01. ICR #19: Soil contaminated by petroleum products, interim cleanup report (Monitoring - September 2000) received 11-8-00. 4 - ICR #1: Soil contaminated by petroleum products, interim cleanup report received date unknown. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 12-23-97.
27	JEFFERSON ST BUS BARN	1398 E JEFFERSON ST	ICR, CSCSL	Petroleum	Soil	Lander and Hanford CS	1 - CSCSL: Soil (confirmed) affected by contaminants petroleum products (confirmed), halogenated organic compounds (suspected), EPA priority pollutants - metals and cyanide (suspected), and inorganic conventional contaminants (suspected), as entered on 3-7-91 2 - ICR: Soil reported contaminated by petroleum products on 1-22-91
28	SEATTLE UNIVERSITY ATHLETIC FIELD II	13TH / CHERRY ST.	ICR	Halogenated Organics, metals, and Petroleum	Soil and Groundwater	Lander and Hanford CS	ICR: Groundwater and soil reported contaminated by halogenated organic compounds, metals, and petroleum products, final cleanup report received on 12-4-91
29	GOODWILL INDUSTRIES SEATTLE, 'DEARBORN CORPORATION CAMPUS GOODWILL	1400 S LANE ST	CSCSL, Solid Waste Facility Database	Petroleum and Halogenated Organics	Air, Soil, and Groundwater	Lander and Hanford CS	CSCSL: Air (suspected) contaminated by petroleum products (suspected), halogenated organic compounds (suspected), and EPA priority pollutants - metals and cyanide (suspected); Soil and groundwater (confirmed) contaminated by petroleum products (confirmed), halogenated organic compounds (confirmed), and EPA priority pollutants - metals and cyanide (suspected); all entered 8-22-06.
30	ARMORED TRANSPORT OF SEATTLE	1401 E YESLER WAY	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	LUST #1: Soil affected, reported cleaned up, release status date 12-6-01. LUST #2: Soil affected, cleanup started, release status date 12-6-01. ICR: Soil contaminated by petroleum, interim report received 3-27-92.
32	DORSEY PROPERTY	1426 23RD AVE	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 5-21-95. LUST #2: Soil contaminated, cleanup started, release status date 10-26-90. 2 - Soil (confirmed) contaminated by petroleum products (confirmed), entered 5-27-09. VCP in progress. ICR: Soil contaminated by petroleum products, final cleanup report received 5-21-92.
33	WESTERN STEEL CASTING CO	145 SOUTH HORTON	CSCSL (2; NFA), VCP, ICR, LUST, and UST	Petroleum	Soil and Groundwater	Hanford CS	CSCSL NFA and VCP (both 3-2-04) both listed. NFA Type: NFA after assessment, IRAP, or VCP; no further information given. LUST #1: Groundwater contaminated, cleanup started, release status date 11-6-02. LUST #2: Soil contaminated, awaiting cleanup, release status date 5-5-01. LUST #3: Soil contaminated, cleanup started, release status date 11-6-02. LUST #4: Groundwater contaminated, awaiting cleanup, release status date 5-5-01. ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report (Limited Subsurface Investigation) received 9-28-01.
35	PROVIDENCE HOSPITAL	1506 JEFFERSON ST.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, interim cleanup report received 4-22-99
36	B & B AUTO REPAIR SEATTLE, 'UNKNOWN	151 12TH AVE	LUST and UST	NR	Groundwater	Lander and Hanford CS	LUST #1: Ground water affected, cleanup started, release status date 3-19-08.
37	RALPHS CONCRETE PUMPING	1511 RAINIER AVE S	CSCSL	Petroleum, metals, and Cyanide	Soil and Surface Water	Lander and Hanford CS	CSCSL: Soil (confirmed) contaminated by petroleum products (confirmed), and EPA priority pollutants - metals and cyanide (confirmed); surface water (suspected) contaminated by petroleum products (suspected); both entered on 2-5-91.
38	SEATTLE PARKS COLMAN SCHOOL	1515 24TH AVE S	Brownsfield Site List and CSCSL	Suspected corrosive wastes, non-halogenated organics, and halogenated organics	Suspected Soil and Groundwater	Lander and Hanford CS	CSCSL #1: Groundwater and soil (both suspected) contaminated by corrosive wastes (suspected), non-halogenated solvents (suspected), halogenated organic compounds (suspected), entered on 6-19-07.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
40	RALPHS CONCRETE PUMPING VACANT LOT	1517 RAINIER AVE	CSCSL	Petroleum, metals, and inorganic conventional contaminants	Confirmed in Soil; suspected in Air and Groundwater	Lander and Hanford CS	CSCSL: Groundwater (suspected) contaminated by petroleum products (suspected) and EPA priority pollutants - metals and cyanide (suspected); Soil (confirmed contaminated by petroleum products (confirmed), EPA priority pollutants - metals and cyanide (confirmed), and inorganic conventional contaminants (confirmed); Air (suspected) contaminated by petroleum products (suspected) and EPA priority pollutants - metals and cyanide (suspected); all three entered on 4-4-01
42	SWANSON PROPERTY	1526 21ST AVE S	CSCSL	Petroleum	Confirmed in Soil; suspected in Groundwater	Lander and Hanford CS	CSCSL: Soil (confirmed) and groundwater (suspected) contaminated by petroleum products (confirmed for soil, suspected for groundwater), halogenated organic compounds (suspected for both), EPA priority pollutants - metals and cyanide (suspected for both), and metals - other non-priority pollutant metals (suspected for both); both entered on 7-13-05
43	SEATTLE CITY LIGHT - EAST PINE SUBSTATION	1555 23RD AVE	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 8-25-93. LUST #2: Soil contaminated, reported cleaned up, release status date 6-1-95. 2 - ICR: Soil contaminated by petroleum products, final cleanup report received 10-21-93
44	UNOCAL 0166	1590 S DEARBORN ST	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, awaiting cleanup, release status date 8-7-96. LUST #2: Soil contaminated, cleanup started, release status date 11-6-96. LUST #3: Groundwater contaminated, cleanup started, release status date 11-6-96. LUST #4: Groundwater contaminated, awaiting cleanup, release status date 9-7-96. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-11-97. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-29-97. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received date unknown. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-20-98. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-15-97. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-12-98. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report received 11-8-96. ICR #8: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-13-96.
46	SEATTLE CITY LIGHT WELLER ST	1600 S WELLER ST	FIFRA / TSCA Tracking System	NR	NR	Lander and Hanford CS	No detail provided
47	LAKESHORE INVESTMENT CORP./STRICKLAND, 'LEE POLETTI	1622 E. YESLER WAY	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - ICR: Soil contaminated by petroleum products, final cleanup report received 8-31-90 2 - LUST #1: Soil contaminated, cleanup started, release status date 7-2-90. LUST #2: Soil, reported cleaned up, release status date 6-1-95.
48	GIRLIE PRESS PROPERTY	1658 21ST AVE	CSCSL (NFA) and VCP	NR	NR	Lander and Hanford CS	CSCSL NFA (4-5-01) and VCP (4-5-01) both listed, no further information given
49	USDOV DEPT OF VETERANS AFFAIRS, 'VA MEDICAL CENTER, 'VA PSHCS SEATTLE DIVISION	1660 S COLUMBIA WAY	FIFRA / TSCA Tracking System, ICR, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 9-28-95. LUST #2: Groundwater contaminated, cleanup started, release status date 9-28-95. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, final cleanup report received 1-11-99. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 2-28-92. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-16-92. ICR #4: Groundwater contaminated by petroleum products, interim cleanup report received 9-23-91.
53	BELSHAW BROTHERS INC	1750 22ND AVE S	CSCSL, ICR, and UST	Petroleum, MTBE, non-halogenated solvents, halogenated compounds, and PAHs	Soil and Groundwater	Lander and Hanford CS	CSCSL: Soil and groundwater (both confirmed) contaminated by petroleum products (confirmed), MTBE code (suspected), non-halogenated solvents (confirmed), halogenated organic compounds (confirmed), polynuclear aromatic hydrocarbons (PAH)(confirmed); both entered 8-26-02. ICR: Groundwater and soil contaminated by petroleum products, polynuclear aromatic hydrocarbons, and 37, report received 5-16-02.
54	STEWART LUMBER & HARDWARE	1761 RAINIER AVE S	FIFRA / TSCA Tracking System, and HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing	NR	NR	Lander and Hanford CS	No detail provided
55	VECA PLAZA, 'VECA ELECTRIC	1762 AIRPORT WAY S	CERCLIS (NFA), LUST, and UST	Petroleum	Soil and Surface Water	Lander and Hanford CS, Lander West SB	LUST #1: Soil contaminated, cleanup started, release status date 6-19-92. LUST #2: Soil contaminated, reported cleaned up, release status date 5-6-02. ICR #1: Soil contaminated by petroleum products, interim cleanup report received 9-11-98. ICR #2: Surface water contaminated by petroleum products, interim cleanup report received 7-13-92.
59	INTERSTATE BRANDS CORP WONDER BREAD	1805 S MAIN	CSCSL (NFA) and UST	NR	NR	Lander and Hanford CS	CSCSL NFA (7-29-08) listed, NFA Type: NFA after assessment, IRAP, or VCP
60	VIEWS AT MADISON	1823 E MADISON ST	CSCSL (NFA) and VCP	NR	NR	Lander and Hanford CS	CSCSL NFA (5-16-03) and VCP (5-16-03) both listed, no further information given
62	MACMILLAN PIPER	185 S HOLGATE ST	FIFRA / TSCA Tracking System and ICR	NR	NR	Lander and Hanford CS, Lander West SB	No detail provided

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
65	JACK IN THE BOX 4TH & HOLLGATE	1907 4TH AVE S	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - LUST #1: Groundwater contaminated, reported cleaned up, release status date 3-11-03. LUST #2: Soil contaminated, cleanup started, release status date 5-21-95. LUST #3: Soil contaminated, reported cleaned up, release status date 3-11-03. LUST #4: Groundwater contaminated, cleanup started, release status date 5-21-95. 2 - ICR: Soil contaminated by petroleum products, interim cleanup report received 10-16-92.
66	HYDE CANDY COMPANY	1912-1916 E MERCER ST	CSCSL (NFA), VCP, and ICR	Petroleum	Soil	Lander and Hanford CS	A petroleum product impacting soil was reported as spilled 7-23-1998 including a final cleanup report.
67	STAR RENTALS & SALES	1919 4TH AVE S	LUST and UST	NR	Soil and Groundwater	Lander and Hanford CS, Lander West SB	LUST #1: Groundwater contaminated, cleanup started, release status date 1-9-99. LUST #2: Soil contaminated, cleanup started, release status date 1-9-99.
68	TAYLOR EDWARDS WHSE & TRANS SEATTLE	1926 6TH AVE SO	Hazardous Material Reporting System, and UST	Corrosive liquids and Diacetone alcohol	NR	Lander and Hanford CS, Lander West SB	1 - HMIRS: .04 gallons of corrosive liquids N.O.S. reported spilled on 7-20-01. 2 - HMIRS: .00052830 gallons of diacetone alcohol caused a fire, as reported on 8-11-97.
69	TAYLOR EDWARDS	1930 6TH AVE. S.	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS, Lander West SB	LUST #1: Soil contaminated, awaiting cleanup, release status date 6-7-94. LUST #2: Soil contaminated, reported cleaned up, release status date 2-15-95. ICR: Soil contaminated by petroleum products, final cleanup report received 2-23-95.
70	BUDGET RENT A CAR OF WASHINGTON-OREGON, 'ELLIOTT TIRE & SERVICE CO INC	1961 4TH AVE S	CSCSL, LUST, and UST	Petroleum and PAHs	Soil and Suspected Groundwater	Lander and Hanford CS, Lander West SB	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 4-1-05. LUST #2: Soil contaminated, cleanup started, release status date 8-12-03. 2 - CSCSL: Groundwater (suspected) contaminated by petroleum products (suspected), MTBE code (suspected), EPA priority pollutants - metals and cyanide (suspected), and polynuclear aromatic hydrocarbons (PAH); soil (confirmed) contaminated by petroleum products (confirmed), MTBE code (suspected), EPA priority pollutants - metals and cyanide (suspected), and polynuclear aromatic hydrocarbons (PAH); both entered 12-18-01.
74	BETHEL CHRISTIAN CHURCH	200 24TH AVE S	ICIS Integrated Compliance Information System	NR	NR	Lander and Hanford CS	No detail provided
75	ACME POULTRY	2001 21ST AVE. S.	ICR, LUST, and UST	NR	Soil and Groundwater	Lander and Hanford CS	LUST #1: Groundwater contaminated, awaiting cleanup, release status date 4-4-91. LUST #2: Soil contaminated, cleanup started, release status date 9-24-91. LUST #3: Soil contaminated, reported cleaned up, release status date 9-23-03. LUST #4: Groundwater contaminated, cleanup started, release status date 9-24-91. LUST #5: Soil contaminated, cleanup started, release status date 2-19-91. LUST #6: Groundwater contaminated, cleanup started, release status date 2-19-91. LUST #7: Soil contaminated, awaiting cleanup, release status date 4-4-91. LUST #8: Groundwater contaminated, reported cleaned up, release status date 9-23-03.
76	OBERTO SAUSAGE COMPANY	2005 AIRPORT WAY S	FIFRA / TSCA Tracking System, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - LUST: Groundwater contaminated, cleanup started, release status date 4-15-99 2 - ICR: Groundwater contaminated by petroleum products, interim cleanup report received 6-9-99.
77	WB SPRAGUE CO INC, 'SPRAGUE PEST CONTROL (TWO REPORTS)	2005 E MADISON ST	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - CSCSL: Soil (confirmed) affected by petroleum products (confirmed), entered on 8-2-99 2 - ICR: Soil contaminated by petroleum products, final cleanup report received 8-2-99 3 - LUST: Soil contaminated, cleanup started, release status date 6-7-89
78	GAI'S SEATTLE FRENCH BAKING CO, 'GAI'S BAKERY, 'FRANZ BAKERY‎	2006 S WELLER ST	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 4-15-97. LUST #2: Soil contaminated, reported cleaned up, release status date 3-14-02. 2 - ICR #1: Soil contaminated by petroleum products, interim cleanup report received 2-10-99. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 6-13-97.
79	2011 S HANFORD ST	2011 S HANFORD ST	CSCSL (NFA) and ICP	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 12-31-03) both listed, NFA Type: NFA after assessment, IRAP, or VCP, no further information given
80	DAVIS DOOR SERVICE INC	2021 S GRAND ST	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, cleanup started, release status date 12-6-90. LUST #2: Soil contaminated, reported cleaned up, release status date 2-10-04.
81	MACK TRUCKS INC	2025 AIRPORT WAY S	CERCLIS (NFA), LUST, and UST	Petroleum	Soil	Lander and Hanford CS, Lander West SB	LUST #1: Soil contaminated, reported cleaned up, release status date 5-21-95. LUST #2: Soil contaminated, cleanup started, release status date 7-29-94. ICR #1: Soil contaminated by petroleum products, final cleanup report received 7-29-94. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 7-29-94.
82	EAST MADISON VALET CLEANERS FORMER	2034 E MADISON ST	VCP and CSCSL	Petroleum and halogenated organic compounds	Soil and Groundwater	Lander and Hanford CS	CSCSL #1: Groundwater (confirmed) contaminated by halogenated organic (confirmed), entered on 8-6-08. CSCSL #2: Soil (confirmed) contaminated by petroleum products (confirmed) and halogenated organic compounds (confirmed), entered on 8-6-08. 2 VCPs in progress.
87	BLACK & DECKER, 'MOTOR PARTS MACHINE CO INC	2100 AIRPORT WAY S	Solid Waste Facility Database	NR	NR	Lander and Hanford CS	No detail provided
93	ARCO 4090, 'PACIFIC CHEM & CLEANING CO	2200 4TH AVE S	CSCSL (NFA), CERCLIS (NFA), ICR, LUST, and UST	NR	NR	Lander and Hanford CS, Lander West SB	No detail provided

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
94	TOTAL RECLAIM	2200 6TH AVE S	PCB Activity Database and Solid Waste Facility Database	NR	NR	Lander and Hanford CS, Lander West SB	No detail provided
95	SHELL #48358	2200 E. UNION ST.	ICR	Petroleum	Groundwater	Lander and Hanford CS	ICR #1: Groundwater contaminated by petroleum products, interim cleanup report received 11-6-91. ICR #2: Groundwater contaminated by petroleum products, interim cleanup report received 2-20-92. ICR #3: Groundwater contaminated by petroleum products, interim cleanup report received on 12-9-92.
96	FLAJOLE BROTHERS INC	2201 4TH AVE S	ICR, LUST, and UST	Petroleum	Groundwater	Lander and Hanford CS, Lander West SB	1 - ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 7-6-93. 2 - LUST #1: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95.
97	CHEMICAL PROCESSORS INC, 'PARK 90/5, 'STACEY ST SOC 070B83, 'DAMES MOORE S LAB, 'SEATTLE CITY AIRPORT WAY PAINT SHOP, 'KATY FILMS INC, 'WA STATE PATROL CRIME LAB SEATTLE, 'XCYTE THERAPIES AIRPORT WAY, 'OSTEX INTERNATIONAL INC	2203 AIRPORT WAY S STE (100, 200, 250, 300, 301, 360, 400)	CSCSL (NFA), VCP, PCB Activity Database, HMRS	NR	NR	Lander and Hanford CS, Lander West SB	CSCSL NFA (6-21-01) and VCP (6-21-01) both listed; NFA type Restrictive covenant, institutional controls; no further information given
98	COLEMAN BLDG FORMER, 'COLMAN BUILDING	2203 E UNION ST	Brownfields Site List (2), VCP, and CSCSL	Petroleum and halogenated organics	Soil and Groundwater	Lander and Hanford CS	CSCSL #1: Soil (confirmed) contaminated by petroleum products (suspected) and halogenated organic compounds (confirmed), entered on 8-22-05. CSCSL #2: Groundwater (confirmed) contaminated by halogenated organic compounds (confirmed), entered on 8-22-05. 2 VCPs in progress.
99	WELCH INVESTMENT CO	2211 S JACKSON ST	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, reported cleaned up, release status date 3-27-02.
100	DL DUCKEY AUTO FREIGHT INC	2212 RAINIER AVE S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 1-14-91. 2 - ICR #1: Soil contaminated by petroleum products, interim cleanup report 3-14-91. ICR #2: Soil contaminated by petroleum products, final cleanup report received 4-24-00.
101	MOBILE TRUCK SERVICE, A TRAFFIC CONSULTANTS/STANLEY TERMINALS	2214 4TH AVE S	CSCSL (NFA), CERCLIS (NFA), and LUST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - CSCSL NFA (2-29-00), NFA Type: NFA after assessment, IRAP, or VCP 2 - LUST #1: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, reported cleaned up, release status date 2-29-00. LUST #3: Groundwater contaminated, reported cleaned up, release status date 2-29-00. LUST #4: Soil contaminated, cleanup started, release status date 6-1-95. ICR #1: Soil contaminated by petroleum products, interim cleanup report received 10-1-92. ICR #2: Soil and groundwater contaminated by petroleum products, interim cleanup report received 11-23-93.
102	PJ MARKET, 'MONACO, 'SHELL #48358	2220 E UNION ST	CSCSL (NFA), VCP, ICR, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL NFA (3-26-08) and VCP (3-26-08) both listed, no further information given. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 11-12-97. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received? ICR #3: Soil contaminated by petroleum products, interim cleanup report received? ICR #4 : Groundwater contaminated by petroleum products, interim cleanup report received 6-2-93. ICR #5: Groundwater contaminated by petroleum products, interim cleanup report received 11-30-94. ICR #6: Soil contaminated by petroleum products, interim cleanup report received 4-28-95. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-23-95. ICR #8: Groundwater contaminated by petroleum products, interim cleanup report received 5-20-92. ICR #9: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-11-94. ICR #10: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-17-97. ICR #11: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-7-97.
103	PACIFIC IRON & metals	2230 4TH AV S	Solid Waste Facility Database and UST	Metal, Cyanide, and PCBs	Soil and Surface Water	Lander and Hanford CS, Lander West SB	CSCSL: Soil and surface water (both remediated) contaminated by EPA priority pollutants - metals and cyanide (remediated), metals - other non-priority pollutant metals (remediated), and polychlorinated biphenyls (PCBs)(remediated); all entered on 3-1-88.
104	THRIFTY OFFICE FURNITURE	2233 1ST AVE. S.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	ICR: Groundwater and soil contaminated by petroleum products, final cleanup report received 6-2-95.
105	KING COUNTY TRANSIT, 'KING CO DOT METRO TRANSIT POWER DISTRIB	2255 4TH AVE S	CSCSL (NFA), LUST, and UST	NR	Soil	Lander and Hanford CS, Lander West SB	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 12-23-02. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95. 2 - CSCSL NFA (1-23-02), NFA Type: NFA after assessment, IRAP, or VCP, no further information given
108	PEPSI BOTTLING GROUP SEATTLE PLANT, 'ALPAC CORPORATION, 'ALPAC CORP	2300 26TH AVE S	CSCSL (NFA), LUST, and UST	Sodium hydroxide, corrosive wastes, petroleum, and non-halogenated organic compounds	Soil and Groundwater	Lander and Hanford CS	1 - ICR #1: Soil contaminated by sodium hydroxide, interim cleanup report received 5-10-93. ICR #2: Soil contaminated by corrosive wastes, final cleanup report received 11-19-93. ICR #3: Groundwater and soil contaminated by petroleum products, non-halogenated organic compounds, final cleanup report received 10-23-95. 2 - ICR: Groundwater and soil contaminated by petroleum products, final cleanup report received 3-18-96 3 - ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-12-93. 4 - CSCSL NFA (5-29-96), NFA Type: NFA after assessment, IRAP, or VCP; no further information given

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
111	VALLEY MARKET	2338 RAINIER AVE S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, cleanup started, release status date 5-13-91. LUST #2: Soil contaminated, reported cleaned up, release status date 6-1-95.
112	23RD & JACKSON SITE	23RD / S JACKSON	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 1-25-96. LUST #2: Soil contaminated, cleanup started, release status date 8-14-95.
115	U.S. POSTAL SERVICE	2401 3RD AVE. S.	ICR	Petroleum	Soil	Lander and Hanford CS, Lander West SB	ICR: Soil contaminate by petroleum products, interim cleanup report received 10-7-91.
116	EXXON 79532	2401 4TH AVE S	LUST and UST	NR	Soil	Lander and Hanford CS, Lander West SB	LUST #1: Soil contaminated, reported cleaned up, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 6-3-88.
117	US POSTAL SERVICE TERMINAL STATION	2401-2445 3RD AVE. S.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-10-95
118	INDUSTRIAL PLATING CORP, 'IPC INDUSTRIAL PLATING CORP, '2411 6TH AVE SOUTH	2411 6TH AVE S	CERCLIS (NFA), ICIS, and CSCSL	NR	NR	Lander and Hanford CS, Lander West SB	Listed in CERCLIS, ICIS and Confirmed and Suspected contaminated list
119	NORDSTROM CATERING CORP	2415 AIRPORT WAY S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS, Lander West SB	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 11-2-90. 2 - ICR: Soil contaminated by petroleum products, final cleanup report received 12-26-90.
120	SUNNY MONY & RAJAN INC, 'UNOCAL SS 5477 FORMER, '2415 BEACON AVENUE S.	2415 BEACON AVE S	VCP, ICR CSCSL, LUST, and UST	Petroleum, metals, and non-halogenated solvents	Soil and Groundwater	Lander and Hanford CS, Lander East SB	1 - CSCSL: Soil (below cleanup level) contaminated by petroleum products (below cleanup level) and EPA priority pollutants - metals and cyanide; groundwater (confirmed) contaminated by petroleum products (confirmed), halogenated organic compounds (confirmed), and EPA priority pollutants - metals and cyanide (below cleanup level); both entered on 4-6-07. 2 - LUST #1: Groundwater contaminated, monitoring, release status date 7-18-96. LUST #2: Groundwater contaminated, cleanup started, release status date 4-26-94. LUST #3: Soil contaminated, cleanup started, release status date 7-18-96. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-1-97. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-12-98. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1/9/08. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-19-98. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-19-98. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-1-99. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-13-99. ICR #8: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-4-99. ICR #9: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-29-99. ICR #10: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-9-00. ICR #11: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-4-00. ICR #12: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-17-96. ICR #13: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-18-95. ICR #14: Groundwater and soil contaminated by petroleum products, interim cleanup report received? ICR #15: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-22-93. ICR #16: Soil contaminated by petroleum products, interim cleanup report received 6-22-93. ICR #17: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-16-93. ICR #18: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-10-95. ICR #19: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-22-95. ICR #20: Groundwater and soil contaminated by petroleum products, interim cleanup report (February 2001 Quarterly Ground Water Monitoring) received 3-21-01. ICR #21: Groundwater and soil contaminated by petroleum products, interim cleanup report (5/00 Quarterly Ground Water Monitoring) received 10-2-00. ICR #22: Groundwater and soil contaminated by petroleum products, interim cleanup report (Quarterly Ground Water Monitoring - May 2001) received 6-19-01. ICR #23: Groundwater and soil contaminated by petroleum products, interim cleanup report (May 2002 Quarterly Ground Water Monitoring) received 6-28-02. ICR #24: Groundwater and soil contaminated by petroleum products, ICR #25: Groundwater and soil contaminated by petroleum products, interim cleanup report (November 2000 Quarterly Ground Water Monitoring) received 1-4-01. ICR #26: Groundwater and soil contaminated by petroleum products, interim cleanup report (Ground Water Monitoring Quarterly - 8/8/01) received 9-4-01. ICR #27: Groundwater and soil contaminated by petroleum products, interim cleanup report (Quarterly Ground Water Monitoring - November 2001) received 1-4-02. ICR #28: Groundwater and soil contaminated by petroleum products, interim cleanup report (Ground Water Monitoring - August 2000) received 10-30-00. ICR #29: Groundwater and soil contaminated by petroleum products, interim cleanup report (Third Quarter Ground Water Monitoring 2002) received 9-10-02. ICR #30: Groundwater and soil contaminated by petroleum products, interim cleanup report (Fourth Quarter Ground Water Monitoring 2002) received 12-18-02.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
121	LEE & EASTES TANK LINES AIRPORT WAY	2418 AIRPORT WAY S	CSCSL (NFA), CERCLIS (NFA), ICR, and LUST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - CSCSL NFA (9-13-95), NFA Type: Cleaned up under prior authority, no further information given. LUST #1: Groundwater contaminated, cleanup started, release status date 7-6-95. LUST #2: Soil contaminated, cleanup started, release status date 7-6-95. LUST #3: Soil contaminated, reported cleaned up, release status date 7-11-03. LUST #4: Groundwater contaminated, reported cleaned up, release status date 7-11-03. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-22-98. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 7-31-95. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-7-95.
122	UNKNOWN, 'SEATTLE SOLID WASTE UTILITY, 'SHELL STATION 120984, 'SHELL #20597 (TWO REPORTS)	2424 BEACON AVE S	VCP, ICR CSCSL, and LUST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander East SB	1 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed) and metals - other non-priority pollutant metals (below cleanup level), entered on 12-23-08. LUST #2: Groundwater contaminated, cleanup started, release status date 9-28-95. LUST #2: Soil contaminated, cleanup started, release status date 9-28-95. 2 VCPs in progress. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-4-99. ICR #2: Groundwater and soil contaminated by petroleum products, final cleanup report received 6-19-00. ICR #3: Groundwater contaminated by petroleum products, interim cleanup report received 11-6-91. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-20-92. ICR #5: Groundwater contaminated by petroleum products, interim cleanup report received 5-20-92. ICR #6: Groundwater contaminated by petroleum products, interim cleanup report received? ICR #7: Groundwater contaminated by petroleum products, interim cleanup report received 12-6-93. ICR #8: Groundwater contaminated by petroleum products, interim cleanup report received 5-25-94. ICR #9: Groundwater contaminated by petroleum products, interim cleanup report received 12-1-04. ICR #10: Groundwater contaminated by petroleum products, interim cleanup report received 5-9-95. ICR #11: Groundwater and soil contaminated by petroleum products, interim cleanup report received 11-17-95. ICR #12: Groundwater and soil contaminated by petroleum products, interim cleanup report (Semiannual Monitoring - February 2001) received 5-11-01. ICR #13: Groundwater and soil contaminated by petroleum products, interim cleanup report (Monitoring - August 2000) received 11-20-00. ICR #14: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-7-97. 3 - ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-4-01.
124	CAREER LINK, 'BIRTH TO 3 CONTRACTS, 'SEATTLE SCHOOL DIST JOHN STANFORD CENTER, 'SEATTLE GENERAL MAIL FACILITY (TWO REPORTS), 'LINCOLN HIGH SCHOOL	2445 3 AV S	CSCSL (NFA), VCP, Institutional Control Site List, ICR, and UST	Petroleum, PCBs, VOCs	Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - CSCSL NFA (4-5-99) and VCP (4-5-99) both Restrictive Covenant, Institutional Controls NFA type, no further information given. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, PCB's, volatile organic compounds, interim cleanup report received 9-15-98. ICR #2: Soil contaminated by total petroleum hydrocarbons, interim cleanup report received 1-5-94.
125	INDUSTRIAL WAREHOUSE	2450 6TH AVE S	CSCSL (NFA), VCP, and UST	NR	NR	Lander and Hanford CS, Lander West SB	CSCSL NFA and VCP (both 9-9-04) both listed, NFA Type: restrictive covenant, institutional controls, no further information given.
127	HARCROS CHEM-SEATTLE BRANCH	2450 EIGHTH AVE S	RCRA Administrative Action Tracking System	NR	NR	Lander and Hanford CS, Lander West SB	No detail provided
128	SHELL STATION 120993, 'TEXACO #63 232 0043, 'LANDERS ST. SHELL	2461 4TH AVE S	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed), both entered 1-12-09. LUST #1: Soil contaminated, cleanup started, release status date 5-13-92. LUST #2: Groundwater contaminated, monitoring, release status date 11-15-93. LUST #3: Groundwater contaminated, cleanup started, release status date 5-13-92. LUST #4: Soil contaminated, monitoring, release status date 11-15-93. 2 VCPs in progress. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-18-98. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 11-19-97. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-7-98. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 11-10-98. ICR#5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-30-99. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-13-00. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-10-00. ICR #8: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-1-96. ICR #9: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-16-93. ICR #10: Soil contaminated by petroleum products, interim cleanup report received 6-16-93. ICR #11: Groundwater contaminated by petroleum products, interim cleanup report received 4-7-95. ICR #12: Groundwater contaminated by petroleum products, interim cleanup report received 5-22-95. ICR #13: Groundwater contaminated by petroleum products, interim cleanup report received 8-18-95. ICR #14: Groundwater contaminated by petroleum products, interim cleanup report received 1-4-95. ICR #15: Groundwater and soil contaminated by petroleum products, interim cleanup report received 7-5-96. ICR #16: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-26-00. ICR #17: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-3-01. ICR #18: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-1-97.
129	SEARS SERVICE STA FORMER, 'SEARS SERVICE STATION (FORMER)	2465 1ST AVE S	CSCSL (NFA)m VCP, ICR, and UST	Petroleum	Soil	Lander and Hanford CS, Lander West SB	1 - CSCSL NFA and VCP (both 6-18-07) both listed, NFA Type: NFA after assessment, IRAP, or VCP, no further information given 2 - ICR #1: Soil contaminated by petroleum products, final cleanup report received 11-7-94. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 11-7-94.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
130	TIME OIL CO 216, 'TIME OIL BULK PLANT (TWO REPORTS)	2465 S COLLEGE ST	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL: Soil (confirmed) contaminated by petroleum products (confirmed), entered on 2-15-07. LUST #1: Soil contaminated, awaiting cleanup, release status date 9-1-93. LUST #2: Groundwater contaminated, awaiting cleanup, release status date 9-1-93. LUST #3: Groundwater contaminated, monitoring, release status date 3-10-06. LUST #4: Soil contaminated, monitoring, release status date 3-10-06. LUST #5: Soil contaminated, cleanup started, release status date 3-31-94. LUST #6: Groundwater contaminated, cleanup started, release status date 3-31-94. 1 VCP in progress. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-26-97. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 11-30-93. ICR #3: Soil contaminated by petroleum products, interim cleanup report received 7-18-94. ICR #4: Soil contaminated by petroleum products, interim cleanup report received 9-22-94. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 7-10-96. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-8-96. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report (Interim TPH Analysis 1998) received 6-24-99. ICR #8: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-30-96. ICR #9: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-23-96. ICR #10: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-16-97.
131	PORT OF SEATTLE MARINE MAINT SHOP, 'SEATTLE PORT SEAPORT MAINTENANCE	25 S HORTON ST	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #3: Groundwater contaminated, reported cleaned up, release status date 1-6-98. LUST #4: Soil contaminated, reported cleaned up, release status date 1-6-98. 2 - ICR #1: Groundwater and soil contaminated, final cleanup report received 1-22-96. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-29-93. ICR #3: Groundwater contaminated by petroleum products, interim cleanup report 9-7-93.
132	CRESCENT FOODS WAREHOUSE	25 SOUTH HANFORD ST.	ICR	Petroleum	Soil and Groundwater	Hanford CS, Hinds SB	ICR: Groundwater and soil reported contaminated by petroleum products, interim cleanup report received 12-6-90.
134	U HAUL CO OF RAINIER AVE S	2515 RAINIER AVE S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST: Soil contaminated, cleanup started, release status date 8-31-98. 2 - ICR: Soil contaminated by petroleum products, interim cleanup report (Site Characterization) received 7-10-00.
136	LAGO VISTA APARTMENTS	2525 14TH AVE S	ICR	Petroleum	Soil	Lander and Hanford CS, Lander East SB	ICR: Soil contaminated by petroleum products, interim cleanup report received 9-8-99.
137	PHOENIX OIL CO INC	2535 AIRPORT WAY S	LUST and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	LUST #1: Soil contaminated, cleanup started, release status date 8-17-04. LUST #2: Groundwater contaminated, cleanup started, release status date 8-17-04.
138	DEENY CONSTRUCTION CO INC	2545 RAINIER AVE S	ICR, ICIS, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST: Soil contaminated, cleanup started, release status date 8-31-92. 2 - ICR: Soil contaminated by petroleum products, interim cleanup report received 9-23-96.
141	TEXACO #0043 (TWO REPORTS)	2641 4TH AVE. S.	ICR	Petroleum	Groundwater	Lander and Hanford CS, Lander West SB	ICR: Groundwater contaminated by petroleum products, interim cleanup report received 2-5-96.
142	SEAFAB metals CO	2700 16TH AVE SW	Corrective Action Report, CERCLIS, and RCRA Administrative Action Tracking System	metals and Cyanide	Soil and Groundwater	Lander and Hanford CS, Lander East SB	CSCSL: Groundwater and soil (confirmed) contaminated by EPA priority pollutants - metals and cyanide (confirmed), both entered 3-1-88.
143	KAPLAN PAPER CO	2700 4TH AVE S	FIFRA / TSCA Tracking System	NR	NR	Lander and Hanford CS, Lander West SB	No detail provided
144	SEATTLE CITY ESD AIRPORT WAY, 'SEATTLE WATER OPERATIONS, 'SEATTLE PUBLIC UTILITIES OPERATIONS CTR	2700 AIRPORT WAY S	ICR and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-4-97. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-18-94. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-8-96. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-9-96. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-19-95. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-2-97. 2 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed), entered on 10-25-91.
145	SEATTLE WA LINE SEG 51 PRINT 448	2700 OCCIDENTAL ST S	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - LUST #1: Soil contaminated, cleanup started, release status date 3-23-95. LUST #2: Groundwater contaminated, cleanup started, release status date 3-23-95. 2 - ICR #1: Soil contaminated by petroleum products, interim cleanup report received 10-25-99. ICR #2: Soil contaminated by petroleum products, final cleanup report received 2-21-95.
146	GRETAG SYSTEMS, 'LOWES HIW 004	2700 RAINIER AVE S	FIFRA / TSCA Tracking System, CERCLIS (NFA)	NR	NR	Lander and Hanford CS	No detail provided
147	KWIK CLEANERS	2701 15TH AVE S	VCP and CSCSL	Halogenated Organics	Soil and Groundwater	Lander and Hanford CS, Lander East SB	1 - CSCSL: Soil and groundwater (both confirmed) contaminated by halogenated organic compounds (confirmed), both entered on 8-8-01. 2 - 2 VCPs in progress
152	RESIDENCE	2715 34TH AVE. S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, interim cleanup report received 6-5-96.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
155	NEWELL PROPERTIES	2730 4TH AVE S	ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	CSCSL: Groundwater and soil (confirmed) contaminated by petroleum products (confirmed), entered 7-10-09. LUST #1: Soil contaminated, cleanup started, release status date 9-13-94. LUST #2: Groundwater contaminated, monitoring, release status date 6-1-95. LUST #3: Groundwater contaminated, cleanup started, release status date 9-13-94. LUST #4: Soil contaminated, monitoring, release status date 6-1-95. ICR #1: Soil contaminated by petroleum products, interim cleanup report received 4-9-98. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 1-20-97. ICR #3: Soil and groundwater contaminated by petroleum products, interim cleanup report received 10-26-99. ICR #4: Soil and groundwater contaminated by petroleum products, interim cleanup report received 10-12-98. ICR #5: Soil and groundwater contaminated by petroleum products, interim cleanup report received 12-7-94. ICR #6: Soil and groundwater contaminated by petroleum products, interim cleanup report received 12-10-01.
156	RABANCO MATERIAL RECOVERY AND RECYCLING, 'RABANCO RECYCLING TRANSFER STATION (3RD & LANDER)	2733 3DR AVE S	Solid Waste Facility Database	NR	NR	Lander and Hanford CS, Lander West SB	Listed on Solid Waste Facility Database
157	WESTERN PETROLEUM	2739 4TH AVE S	LUST and UST	NR	NR	Lander and Hanford CS, Lander West SB	LUST #1: Soil contaminated, reported cleaned up, release status date 5-21-95. LUST #2: Soil contaminated, cleanup started, release status date 6-26-89.
158	AUSTIN MACK	2739 6TH AVE S	CSCSL (NFA), LUST, and UST	NR	NR	Lander and Hanford CS, Lander West SB	CSCSL NFA (5-25-89) listed, NFA Type: cleaned up under prior authority; no further information given.
159	CHEVRON 2740 1ST S	2740 1ST AVE S	CSCSL (NFA), ICR, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - CSCSL NFA (4-10-09) listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given 2 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received date unknown. ICR #2 Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-13-99. ICR #3 Soil contaminated by petroleum products, interim cleanup report received date unknown. ICR #4 Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-7-94. ICR #5 Groundwater and soil contaminated by petroleum products, interim cleanup report received 7-25-96. ICR #6 Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-4-95. ICR #7 Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-16-00. ICR #8 Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-4-00. ICR #9 Groundwater and soil contaminated by petroleum products, interim cleanup report (Ground Water Monitoring and Sampling) received 1-29-02. ICR #10 Groundwater and soil contaminated by petroleum products, interim cleanup report (Ground Water Sampling - June, September, November 2001) received 5-7-01. ICR #11 Groundwater and soil contaminated by petroleum products, interim cleanup report (Ground Water Monitoring - March 2000) received 5-15-00. ICR #12: Groundwater and soil contaminated by petroleum products, interim cleanup report (Sampling - December 2000) received 2-6-01. ICR #13: Groundwater and soil contaminated by petroleum products, interim cleanup report (Ground Water Monitoring February & August 2002) received 10-18-02.
161	CHEVRON #9 9168 (TWO REPORTS)	2751 1ST AVE. S.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	ICR: Groundwater and soil contaminated by petroleum products, final cleanup report received 3-23-93.
162	6TH AVE S LANDFILL 2752 6TH AVE S	2752 6TH AVE S	CSCSL (NFA)	NR	NR	Lander and Hanford CS, Lander West SB	CSCSL NFA (11-12-97), NFA Type: NFA after assessment, IRAP, or VCP, no further information given
163	SEARS AUTO SERVICE CENTER, 'SEARS AUTOMOTIVE CENTER FORMER	2753 UTAH AVE.	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Suspected Groundwater	Lander and Hanford CS, Lander West SB	1 - ICR #1: Soil contaminated by petroleum products, interim cleanup report receive 1-19-93. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-10-93. 2 - CSCSL: Soil (confirmed) contaminated by petroleum products (confirmed); groundwater (suspected) contaminated by petroleum products (suspected); both entered 3-29-07. 2 VCPs in progress. 3 - LUST: Soil contaminated, cleanup started, release status date 6-1-95.
164	SEARS UNIT 6239, 'SEARS UNIT 6239 FORMER	2759 1ST AVE S	VCP and CSCSL	Petroleum	Suspected Soil and Groundwater	Lander and Hanford CS, Lander West SB	CSCSL: Soil (suspected) contaminated by petroleum products (suspected) entered 3-15-07. 1 VCP in progress.
165	ELEPHANT CAR WASH	2763 4TH AVE S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS, Lander West SB	LUST #1: Soil contaminated, cleanup started, release status date 9-16-93. LUST #2: Soil contaminated, reported cleaned up, release status date 9-16-93. ICR: Soil contaminated by petroleum products, final cleanup report received 9-16-93.
166	FORMER GAS STATION 2800 M L KING JR WY, 'PHILLIPS 66 070644	2800 MARTIN LUTHER KING JR WAY S	VCP, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed), both entered on 10-12-07. LUST #1: Soil contaminated, awaiting cleanup, release status date 8-11-05. LUST #2: Groundwater contaminated, awaiting cleanup, release status date 8-11-05. LUST #3: Groundwater contaminated, cleanup started, release status date 8-26-05. LUST #4: Soil contaminated, cleanup started, release status date 8-26-05. 2 VCPs in progress
167	CHEVRON USA INC 90333, 'RAINIER AVE CHEVRON	2802 RAINIER AVE S	VCP, CSCSL, LUST and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed), both entered on 5-2-05. 2 VCPs in progress. 2 - LUST #1: Groundwater contaminated, awaiting cleanup, release status date 6-1-95. LUST #2: Soil contaminated, awaiting cleanup, release status date 6-1-95.
168	MOUNT BAKER APARTMENTS	2900 S. MCCLELLAN ST.	ICR	Petroleum	NR	Lander and Hanford CS	ICR: Unknown contaminated by petroleum products, report received 4-23-90
169	CHIN BROTHERS INC, 'CL AUTO REPAIR	2901 17TH AVE S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 8-28-01. LUST #2: Soil contaminated, awaiting cleanup, release status date 3-13-01. 2 - ICR: Soil contaminated by petroleum products, final cleanup report (Site Assessment and Site Closure Report) received 10-5-01.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
170	FRANZ SEATTLE, 'UNITED STATES BAKERY, FRANZ NORTHERN DIV OF U S BA, 'LANGENDORF BREAD	2901 6TH AVE S	CERCLIS (NFA), ICR, CSCSL, LUST, and UST	Pesticides, Petroleum, metals and Cyanide, PCBs, and inorganic conventional contaminants	Suspected Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - CSCSL: Soil and groundwater (both suspected) contaminated by pesticides (suspected), petroleum products (suspected), EPA priority pollutants - metals and cyanide (suspected), metals - other non-priority pollutant metals (suspected), polychlorinated biphenyls (PCBs)(suspected), inorganic conventional contaminants (suspected); both entered on 3-1-88. 2 - LUST #1: Soil contaminated, reported cleaned up, release status date 1-9-02. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95. 3 - ICR #1: Soil contaminated by petroleum products, interim cleanup report received 12-5-97. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 1-29-99. ICR #3: Soil contaminated by petroleum products, interim cleanup report received 3-5-99.
172	CITY VIEW ASSOCIATES LLC, 'CITY VIEW APARTMENTS	2901 S JACKSON ST	CSCSL (NFA)m VCP and ICR	NR	NR	Lander and Hanford CS	1 - CSCSL NFA and VCP (both 5-9-01) both listed, NFA Type: NFA after assessment, IRAP, or VCP, no further information given 2 - Soil contaminated by petroleum products, final cleanup report (Limited Phase II Investigation) received 2-16-01.
173	SCHUCKS AUTO SUPPLY 4TH AVE	2905 4TH AVE S	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	LUST #1: Groundwater contaminated, cleanup started, release status date 10-2-98. LUST #2: Soil contaminated, cleanup started, release status date 10-2-98. ICR: Groundwater and soil contaminated by petroleum products, final cleanup report received 10-2-98.
174	FIRESTONE STORE 31A8, 'RAINIER FIRESTONE TIRE STORE AND SHOP	2915 RAINIER AVE	ICR and UST	NR	NR	Lander and Hanford CS	No detail provided
175	CHAN PROPERTY	2918 1ST AVE S	CSCSL	metals and Cyanide	Soil and Groundwater	Lander and Hanford CS, Lander West SB	CSCSL: Groundwater (confirmed) and soil (below cleanup level) contaminated by EPA priority pollutants - metals and cyanide (confirmed in groundwater, below cleanup level in soil), both entered on 10-24-06.
176	ALLIED DOMEQ	2921 MARTIN LUTHER KING JR WAY S	VCP, CSCSL, LUST, and UST	Petroleum, non-halogenated solvents, and metals	Soil and Groundwater	Lander and Hanford CS	1 - 2 VCPs in progress 2 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (both confirmed), non-halogenated solvents (remediated for groundwater, confirmed for soil), and metals - other non-priority pollutant metals (only for groundwater, confirmed); both entered on 7-30-03. 3 - LUST #1: Groundwater contaminated, cleanup started, release status date 3-24-98. LUST #2: Soil contaminated, cleanup started, release status date 3-24-98. LUST #3: Soil contaminated, monitoring, release status date 11-7-07. LUST #4: Groundwater contaminated, monitoring, release status date 11-7-07.
177	2929 16TH AVE, 'LOCKHEED SHIPBLDG CO YARD 1	2929 16TH AVE	CERCLIS, ICR, ICIA, CSCSL, and Material Licensing Tracking System	Petroleum, halogenated organic compounds, metals, pesticides, and PAHs	Soil, Groundwater and Sediment	Lander and Hanford CS	CSCSL: Groundwater (confirmed) contaminated by petroleum products (confirmed), halogenated organic compounds (suspected), and EPA priority pollutants - metals and cyanide (confirmed); Sediment (confirmed) contaminated by pesticides (suspected), petroleum products (confirmed), phenolic compounds (suspected), non-halogenated solvents (suspected), EPA priority pollutants - metals and cyanide (confirmed), polychlorinated biphenyls (PCBs)(confirmed), polynuclear aromatic hydrocarbons (PAHs)(confirmed), organic and inorganic conventional contaminants (both suspected), and tributyltin contaminant group (confirmed); soil (confirmed) contaminated by petroleum products (confirmed), EPA priority pollutants - metals and cyanide (confirmed), PCBs (confirmed), and PAHs (confirmed); surface water (suspected) contaminated by petroleum products (suspected) and halogenated organic compounds (suspected); all four entered on 3-1-88. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-2-92. Soil contaminated by petroleum products, interim cleanup report received 10-4-93. Soil contaminated by petroleum products, interim cleanup report received 1-4-93.
178	NORTHWEST MOTOR REPAIR	2930 6TH AVE S	LUST and UST	NR	Soil	Lander and Hanford CS, Lander West SB	LUST #1: Soil contaminated, reported cleaned up, release status date 5-21-95. LUST #2: Soil contaminated, cleanup started, release status date 12-11-89.
179	BURLINGTON NORTHERN	2943 COLORADO AVE. S.	ICR	Petroleum	Soil	Lander and Hanford CS, Lander West SB	ICR: Soil contaminated by petroleum products, interim cleanup report received 12-18-98
180	GROWING GREEN INTERIORS UST 100413	2959 1ST AVE S	LUST and UST	NR	Soil	Lander and Hanford CS, Lander West SB	LUST: Soil contaminated, cleanup started, release status date 6-1-95
181	ANDY'S DINER	2963 4TH AVE. S.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	ICR: Groundwater and soil reported contaminated by petroleum products, interim cleanup report received 3-24-93.
182	SEATTLE CITY ROW 2ND & SPOKANE	2ND AVE S / S SPOKANE ST	CSCSL	Petroleum, metals and Cyanide, organic and conventional contaminants	Suspected Soil and Groundwater	Hanford CS	CSCSL: Soil (suspected) contaminated by petroleum products (below cleanup level), EPA priority pollutants - metals and cyanide (suspected), metals - other non-priority pollutant metals (suspected), organic and inorganic conventional contaminants (both suspected); Groundwater (suspected) contaminated by petroleum products (suspected), EPA priority pollutants - metals and cyanide (below cleanup level), and organic and inorganic conventional contaminants (both suspected); both entered 9-30-02.
183	PACIFIC TRUCKING SEATTLE	300 S SPOKANE ST	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Hanford CS	1 - CSCSL: Groundwater (remediated) contaminated by petroleum products (remediated); Soil (confirmed) contaminated by petroleum products (confirmed); both entered 6-10-97. LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, reported cleaned up, release status date 12-9-95. 2 - ICR: Groundwater and soil contaminated by petroleum products, final cleanup report received 10-12-95.
184	CECIL LEUNG, 'IMPERIAL RICHFIELD	3005 RAINIER AVE S	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Groundwater contaminated, cleanup started, release status date 8-21-98. LUST #2: Soil contaminated, cleanup started, release status date 8-21-98. 2 - ICR #1: Soil contaminated by petroleum products, interim cleanup report received 8-21-98. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 7-30-98.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
186	RAINIER BREWERY CO, 'G HEILEMAN BREWING CO	3100 AIRPORT WAY S	FIFRA / TSCA Tracking System, ICR, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, monitoring, release status date 5-18-00. LUST #3: Groundwater, cleanup started, release status date 6-1-95. LUST #4: Groundwater contaminated, monitoring, release status date 5-18-00. 2 - CSCSL: Soil (remediated) contaminated by petroleum products (remediated); Groundwater (confirmed) contaminated by petroleum products (confirmed); both entered 1-21-00. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-21-00. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-18-00. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-16-00. ICR #4: Soil contaminated by petroleum products, interim cleanup report received 11-29-90. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report (Remedial Investigation/Feasibility Study/Cleanup Action Plan) received 1-15-02.
187	3A INDUSTRIES INC	3101 MARTIN LUTHER KING JR WAY S	VCP and CSCSL	Non-halogenated, halogenated organics and Petroleum	Soil and Groundwater	Lander and Hanford CS	CSCSL: Groundwater (confirmed) contaminated by non halogenated solvents (below cleanup level), and halogenated organic compounds (confirmed); Soil (below cleanup level) contaminated by petroleum products (suspected), non-halogenated solvents (below cleanup level), and halogenated organic compounds (below cleanup level); both entered 8-17-04. 2 VCPs in progress.
188	SUN PROPERTY	3114 12TH AVE S	CSCSL (NFA) and CSCSL	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 12-5-01) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given.
192	ANDYS DINER INC	3201 4TH AVE S	LUST and UST	NR	Soil and Groundwater	Lander and Hanford CS	LUST #1: Groundwater contaminated, cleanup started, release status date 3-24-93. LUST #2: Soil contaminated, cleanup started, release status date 3-24-93.
194	SCALZO COMPANY	3211 AIRPORT WAY S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, interim cleanup report received 2-16-94
195	PACIFIC EXPRESS	3215 4TH AVE S	CSCSL, LUST, and UST	Petroleum and non-halogenated solvents	Soil, Groundwater, and Suspected Air	Lander and Hanford CS	1 - CSCSL: Air (suspected), groundwater (confirmed), soil (confirmed) contaminated by petroleum products (suspected in air, confirmed in groundwater in groundwater and soil) and non-halogenated solvents (suspected in air, confirmed in groundwater in groundwater and soil); all three entered 2-9-04. 2 - LUST #1: Groundwater contaminated, awaiting cleanup, release status date 5-1-98. LUST #2: Soil contaminated, cleanup started, release status date 1-21-00. LUST #3: Soil contaminated, awaiting cleanup, release status date 5-1-98. LUST #4: Groundwater contaminated, cleanup started, release status date 1-21-00.
196	BP/SOUTHCENTER OIL/PACIFIC EXPRESS	3215 4TH AVE. S.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	ICR #1: Soil contaminated by petroleum products, interim cleanup report received 7-31-98. ICR #2: Groundwater contaminated by petroleum products, interim cleanup report received 8-9-99. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-27-99. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-2-99. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 9-10-98. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 7-31-98. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-17-00. ICR #8: Groundwater and soil contaminated by petroleum products, interim cleanup report (Sampling - April 2000) received 5-30-00. ICR #9: Groundwater and soil contaminated by petroleum products, interim cleanup report (Quarterly Status) received 6-28-01. ICR #10: Groundwater and soil contaminated by petroleum products, interim cleanup report (Results of Third Quarter 2000 Ground Water Monitoring) received 11-27-00. ICR #11: Groundwater contaminated by metals, total petroleum hydrocarbons, 42, interim cleanup report (Results of Fourth Quarter 2001 Ground Water Monitoring) received 1-29-02. ICR #12: Groundwater and soil contaminated by petroleum products, interim cleanup report (Second Quarter 2000 Ground Water Monitoring) received 8-21-00. ICR #13: Groundwater and soil contaminated by petroleum products, interim cleanup report (Monitoring - October 1999) received 11-30-99. ICR #14: Groundwater and soil contaminated by petroleum products, interim cleanup report (July 2002 Ground Water Monitoring Report - Third Quarter) received 9-30-02.
197	SEATTLE BEST CLEANERS, 'BEACON MARKET	3219 MARTIN LUTHER KING JR WAY S	ICR, CSCSL, LUST, and UST	Halogenated Organic Compounds	Soil	Lander and Hanford CS	1 - CSCSL: Soil (confirmed) contaminated by halogenated organic compounds (confirmed), entered 2-16-09. LUST: Soil contaminated, awaiting cleanup, release status date 10-27-08. 2 - Soil contaminated by petroleum products, interim cleanup report received 11-12-92.
198	ALASKA COPPER & BRASS	3223 6TH AVE S	CSCSL	Corrosive Wastes, metals and Cyanide,	Suspected Soil and Groundwater	Lander and Hanford CS	CSCSL: Groundwater and soil (suspected) contaminated by reactive wastes (suspected), corrosive wastes (suspected), EPA priority pollutants - metals and cyanide (suspected), inorganic conventional contaminants (suspected); both entered 3-1-88.
199	SEATTLE FIRE STATION 14	3224 4TH AVE S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST: Soil contaminated, cleanup started, release status date 2-14-00. 2 - ICR: Soil contaminated by petroleum products, interim cleanup report (Site Characterization Report) received 5-21-02
203	KING CO HARBORVIEW MEDICAL CTR	325 9TH AVE		Petroleum	Soil	Lander and Hanford CS	ICR #1: Soil affected by petroleum products, interim report received 9-4-91. ICR #2: Soil affected by petroleum products, interim report received 4-14-92.
204	HARBORVIEW MEDICAL CENTER	325 NINTH AVENUE	LUST	NR	Soil	Lander and Hanford CS	LUST #1: Soil affected, cleanup started, release status date 4-3-91. LUST #2: Soil affected, reported cleaned up, release status date 4-20-00.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
205	ROADWAY EXPRESS INC	3300 6TH AVE S	HMRS	See Detailed Excerpts	NR	Lander and Hanford CS	1 - HMIRS: .02343750 gallons of compound cleaning liquid reported spilled. 2 - HMIRS: .0625 gallons of hydrogen peroxide (20-40%) reported spilled 10-23-92 3 - HMIRS: 1 gallon of iodate solution reported spilled on 7-31-94 4 - HMIRS: .5 gallons of adhesives reported spilled on 8-31-94 5 - HMIRS: 10 gallons of isopropanol reported spilled on 10-5-97 6 - HMIRS: .5 gallons of film developer reported spilled on 8-28-98. 7 - HMIRS: .046875 gallons of toxic liquids cor organic reported spilled on 7-16-96 8 - HMIRS: .125 pounds of calcium hypochlorite dry reported spilled on 7-24-97 9 - HMIRS: .25 gallons of methanol reported spilled on 10-16-92 10 - HMIRS: 1 gallon of resin solution reported spilled on 10-28-92 11 - HMIRS: .03125 gallons of alkylamines N.O.S. CORROS reported spilled on 2-8-94 12 - HMIRS: 4 gallons of Targo wet or dry spo reported spilled on 3-20-94 13 - HMIRS: .125 gallons of corrosive liquids N.O.S. reported spilled on 1-26-95 14 - HMIRS: 5 gallons of hydrocarbons liquid NOS reported spilled on 10-5-96 15 - HMIRS: 2 gallons of aquathall k reported spilled on 6-2-90 16 - HMIRS: 17 - HMIRS: 3 gallons of ink printers flammable reported spilled on 3-20-99 18 - HMIRS: 10 gallons of printing ink flammable reported spilled on 5-4-98 19 - HMIRS: .5 gallons of resing solution reported spilled on 1-29-02 20 - HMIRS: 5 pounds of alkyl sulfonic acid solids reported spilled on 9-21-98 21 - HMIRS: 3 gallons of phosphoric acid reported spilled on 6-13-02 22 - HMIRS: .0078125 gallons of compressed gas NOS reported spilled on 9-9-97 23 - HMIRS: 2 gallons of adhesives reported spilled on 10-13-94 24 - HMIRS: Magnesium nitrate reported spilled on 8-24-00 25 - HMIRS: .05 gallons of 5-chloro-2-methyl-4-? reported spilled 6-11-02 26 - HMIRS: 1 gallon of aromatic ethanol reported spilled on 3-24-00 27 - HMIRS: 1 gallon of aromatic ethanol reported spilled on 3-24-00 28 - HMIRS: 1 gallon of adhesives reported spilled on 6-6-02
206	LOVSTEAD INDUSTRIES	3300 AIRPORT WY S	CSCSL (NFA)	NR	NR	Lander and Hanford CS	CSCSL NFA (9-10-91) listed, NFA Type: cleaned up under prior authority
209	BURGER KING SITE	3301 4TH AVE S	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 7-10-02. LUST #2: Soil contaminated, cleanup started, release status date 5-21-95. 2 - ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-11-90.
212	REI WOODWORKING (FORMER)	3314 4TH AVE. S.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	ICR #1: Groundwater and soil contaminated by petroleum products, final cleanup report received 5-20-96. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-15-96.
214	RESIDENTIAL UST	3328 CASCADIA AVE.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, final cleanup report received 12-27-93
215	CHUBBY AND TUBBY SITE	3333 RAINIER AVE S	Brownsfield Listing, CERCLIS (NFA), CSCSL, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - CSCSL: Soil (confirmed) contaminated by petroleum products (below cleanup level) and EPA priority pollutants - metals and cyanide (below cleanup level), entered on 9-30-08. 2 - LUST #1: Soil contaminated, reported cleaned up, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 6-12-91. ICR: Soil contaminated by petroleum products, final cleanup report received 2-11-92.
216	WALKER RESIDENCE	336 18TH AVE. E.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, final cleanup report received 2-3-93
217	AURORA CRANE CORP, TRANSPORT EQUIPMENT CO	3400 6TH AVE S	FIFRA / TSCA Tracking System, ICR, and UST	NR	NR	Lander and Hanford CS	No detail provided
219	ALASKA COPPER & BRASS	3405 6TH AVE. S.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 9-11-90.
222	PRESERVATIVE PAINT COMPANY	3410 AIRPORT WAY S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, interim cleanup report (Phase I Site Assessment) received 8-29-97.
223	NORTHWEST CASTINGS	3411 1ST AVE S	FIFRA / TSCA Tracking System, ICR, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, and ICIS	NR	NR	Hanford CS	No detail provided

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
224	ACME INTERCITY FREIGHT, 'PACKAGE SERVICE INC, 'COMMERCIAL PROPERTY	3414 2ND AVE S	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Surface water and Soil	Hanford CS	1 - CSCSL: Surface water (confirmed) contaminated by petroleum products (suspected), non-halogenated solvents (suspected), and metals - other non-priority pollutant metals (confirmed); Soil (confirmed) contaminated by petroleum products (confirmed) and non-halogenated solvents (suspected); entered on 4-27-96. 2 VCPs in progress. 2 - LUST: Soil contaminated, cleanup started, release status date 7-25-01. 3 - ICR: Soil contaminated by petroleum products, interim cleanup report (UST Closure Site Assessment) received 11-15-01.
225	SASAKI RESIDENCE	3417 18TH AVE S	CSCSL (NFA) and VCP	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 9-30-03) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given
226	ENTERPRISES NW	3422 1ST AVE S	VCP, CSCSL, and UST	Petroleum, metals and Cyanide, PCBs, and PAHs	Soil and Groundwater	Hanford CS	1 - 2 VCPs in progress 2 - CSCSL: Soil (confirmed) and groundwater (confirmed) contaminated by petroleum products (confirmed for soil, suspected for groundwater), EPA priority pollutants - metals and cyanide (only in soil, confirmed), polychlorinated biphenyls (PCBs)(confirmed for both), and polynuclear aromatic hydrocarbons (PAHs)(only for soil, confirmed); both entered on 1-1-07.
228	3433 4TH S PROPERTY, 'BUSINESS PRO COMPUTERS	3433 4TH AVE S	CSCSL (NFA), ICR, and LUST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 3-27-89. LUST #2: Groundwater contaminated, cleanup started, release status date 3-27-89. LUST #3: Soil contaminated, reported cleaned up, release status date 6-15-94. LUST #4: Groundwater contaminated, monitoring, release status date 5-21-95. LUST #5: Soil contaminated, monitoring, release status date 5-21-95. LUST #6: Groundwater contaminated, reported cleaned up, release status date 6-15-94. 2 - CSCSL NFA (11-9-94), NFA Type: Restrictive Covenant, Institutional Controls, no further information given 3 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-1-92. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-21-94.
229	ROADLINK TRANSPORTATION SOLUTIONS	3433 AIRPORT WAY S	PCB Activity Database	PCBs	NR	Lander and Hanford CS	No detail provided
230	CRAIN NW INC	3434 4TH AVE S	CSCSL (NFA), VCP, and UST	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 9-17-02) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information provided
231	PENSKE TRUCK LEASING CO LP, 'ROLLINS LEASING CORP	3443 1ST AVE S	ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Hanford CS	1 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed), both entered on 9-30-02. 2 - ICR: Groundwater and soil contaminated by petroleum products, final cleanup report received date unknown. 3 - LUST: Soil contaminated, cleanup started, release status date 1-17-91.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
232	UNOCAL SS NO 5472	3460 1ST AVE S	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Hanford CS	1 - CSCSL: Soil (below cleanup level) and groundwater (confirmed) contaminated by petroleum products (soil - below cleanup level; groundwater - confirmed); both entered 10-23-98. 2 VCPs in progress. 2 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Groundwater contaminated, monitoring, release status date 6-2-95. LUST #3: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #4: Soil contaminated, monitoring, release status date 6-2-95. 3 - ICR #1: Groundwater and soil contaminated, interim cleanup report received date unknown. ICR #2: Groundwater and soil contaminated, interim cleanup report received 1-28-98. ICR #3: Groundwater and soil contaminated, interim cleanup report received 4-28-98. ICR #4: Groundwater and soil contaminated, interim cleanup report received 7-20-98. ICR #5: Groundwater and soil contaminated, interim cleanup report received 8-14-98. ICR #6: Groundwater and soil contaminated, interim cleanup report received 10-23-98. ICR #7: Groundwater and soil contaminated, interim cleanup report received 11-30-98. ICR #8: Groundwater and soil contaminated, interim cleanup report received 1-15-99. ICR #9: Groundwater and soil contaminated, interim cleanup report received 12-3-98. ICR #10: Groundwater and soil contaminated, interim cleanup report (Monitoring - March 2000) received 6-12-00. ICR #11: Groundwater and soil contaminated, interim cleanup report (Remediation Performance - 11/99 through 7/00) received 8-10-00. ICR #12: Groundwater and soil contaminated, interim cleanup report received 2-2-00. ICR #13: Groundwater and soil contaminated, interim cleanup report received 5-22-92. ICR #14: Groundwater and soil contaminated, interim cleanup report received 3-12-93. ICR #15: Groundwater and soil contaminated, interim cleanup report received 3-13-95. ICR #16: Groundwater and soil contaminated, interim cleanup report received 12-1-95. ICR #17: Groundwater and soil contaminated, interim cleanup report received 12-12-96. ICR #18: Groundwater and soil contaminated, interim cleanup report received 6-7-96. ICR #19: Groundwater and soil contaminated, interim cleanup report (Quarterly Monitoring - First Quarter 1999) received 7-14-99. ICR #20: Groundwater and soil contaminated, interim cleanup report (UST Removal June 1999) received 9-20-99. ICR #21: Groundwater and soil contaminated, interim cleanup report (Ground Water Monitoring - 4th Quarter 2000) received 1-16-01. ICR #22: Groundwater and soil contaminated, interim cleanup report (Third Quarter Ground Water Monitoring 2000) received 12-18-00. ICR #23: Groundwater and soil contaminated, interim cleanup report (Fourth Quarter Ground Water Monitoring 2001) received 1-22-02. ICR #24: Groundwater and soil contaminated, interim cleanup report received. ICR #25: Groundwater and soil contaminated, interim cleanup report (Third Quarter Ground Water Monitoring - August 2001) received 10-30-01. ICR #26: Groundwater and soil contaminated, interim cleanup report (Second Quarter Ground Water Monitoring - June 2001) received 10-30-01. ICR #27: Groundwater and soil contaminated, interim cleanup report (Third Quarter Ground Water Monitoring 2001) received 10-23-01. ICR #28: Groundwater and soil contaminated, interim cleanup report (Tosco Marketing Company Ground Water Monitoring Report) received 7-12-01. ICR #29: Groundwater and soil contaminated, interim cleanup report (Remedial System Quarterly Operation & Maintenance Report) received 6-19-01. ICR #30: Groundwater and soil contaminated, interim cleanup report (Ground Water Monitoring - Quarter 1 and Quarter 2, 2001) received 4-25-01. ICR #31: Groundwater and soil contaminated, interim cleanup report (Ground Water Monitoring - First Quarter 2001) received 1-9-01. ICR #32: Groundwater and soil contaminated, interim cleanup report (Ground Water Monitoring - Third Quarter 2000) received 3-28-97. ICR #33: Groundwater and soil contaminated, interim cleanup report (Ground Water Monitoring Report) received 9-13-00. ICR #34: Groundwater and soil contaminated, interim cleanup report (Fourth Quarter Ground Water Monitoring 2001) received 3-4-02. ICR #35: Groundwater and soil contaminated, interim cleanup report (Third Quarter Ground Water Monitoring 2002) received 11-12-02.
236	ACKERLEY COMMUNICATIONS OF THE NW INC, 'CLEAR CHANNEL OUTDOOR	3601 6TH AVE S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, reported cleaned up, release status date 4-11-00.
237	SEATTLE PUBLIC UTILITIES BEACON HILL RES, 'SEATTLE FIRE STATION 13, 'BEACON RESERVOIR	3601 BEACON AVE S	ICR, LUST, and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, awaiting cleanup, release status date 2-16-00. LUST #2: Soil contaminated, cleanup started, release status date 2-16-00. LUST #3: Soil contaminated, reported cleaned up, release status date 8-2-02.
238	TIME STATION 234	3601 MARTIN LUTHER KING JR WAY	CSCSL (NFA) and UST	NR	NR	Lander and Hanford CS	CSCSL NFA (3-31-09) listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information listed
239	MOUNT BAKER BUILDING (THREE REPORTS)	3601 MCCLELLAN	CSCSL (NFA), VCP, ICR and UST	Petroleum	Soil	Lander and Hanford CS	1 - ICR #1: Soil contaminated by petroleum products, interim cleanup report received 1-30-97. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 1-1-94. Soil contaminated by petroleum products, final cleanup report received 11-26-96. 2 - CSCSL NFA (2-26-98), NFA Type: Restrictive Covenant, Institutional Controls
240	GENESEE SHELL & MINI MART, 'SHELL	3611 GENESEE ST S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 2-23-93. LUST #2: Soil contaminated, cleanup started, release status date 12-1-89 2 - ICR #1: Soil contaminated by petroleum products, final cleanup report received 9-28-92. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 9-28-92. ICR #3: Soil contaminated by petroleum products, interim cleanup report received 12-22-92. ICR #4: Soil contaminated by petroleum products, final cleanup report received 2-23-93.
241	RAINIER COURT PHASE IV (THE HOME OWNERSHIP PROJECT	3612-3656 34TH AVE. SOUTH	Brownfield Listing	NR	NR	Lander and Hanford CS	No detail provided

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
242	SEATTLE CITY LIGHT MRWF, 'SEATTLE CITY LIGHT (FIVE REPORTS)	3613 4TH AV S	FIFRA / TSCA Tracking System, ICR, PCB Activity Database, CERCLIS (NFA), ICR, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, LUST, Solid Waste Facility Database, and UST	Petroleum, Dioxin, and PCBs	Soil, Groundwater and Suspected Air	Lander and Hanford CS	1 - CSCSL: Air, groundwater, and soil (air suspected, groundwater and soil confirmed) contaminated by petroleum products (groundwater and soil only, confirmed), dioxin (suspected for all three), and polychlorinated biphenyls (PCBs)(suspected for all three); entered for all three on 3-1-88. 2 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, reported cleaned up, release status date 7-31-06. LUST #3: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #4 Groundwater contaminated, reported cleaned up, release status date 7-31-06.
243	RAINIER COURT PARCEL O	3616 34TH AVENUE S	Brownfield Listing	NR	NR	Lander and Hanford CS	No detail provided
245	RAINIER COURT PHASE II (THE DAKOTA)	3634-33RD AVE	Brownfield Listing	NR	NR	Lander and Hanford CS	No detail provided
246	DALEYS DUMP TRUCK SERVICE INC	3646 33RD S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 5-13-05. LUST #2: Soil contaminated, cleanup started, release status date 5-11-2005.
247	MCE TECHNOLOGIES INC	3670 E MARGINAL WAY S	VCP, CSCSL, LUST, and UST	Petroleum, arsenic, metals and Cyanide, non-priority	Soil and Groundwater	Hanford CS	CSCSL: Soil and groundwater (both confirmed) contaminated by petroleum products (confirmed), arsenic code (confirmed), EPA priority pollutants - metals and cyanide (confirmed), metals - other non-priority pollutant metals (confirmed), polychlorinated biphenyls (PCBs)(only soil, below cleanup level); both entered 10-12-07. 2 VCPs in progress
248	RAINIER COURT ASSOCIATES 2002-1 LLC	3700 RAINIER AVE S	CSCSL and UST	NR	NR	Lander and Hanford CS	No detail provided
249	LOCKE, 'FLUOROCARBON CO, 'SAINT GOBAIN PERFORMANCE PLASTICS	3711 S HUDSON	FIFRA / TSCA Tracking System, ICR, CSCSL (NFA), VCP, and HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 1-14-03) both listed, NFA Type: NFA after assessment, IRAP, or VCP, no further information given
250	RAINIER PLAZA SEATTLE	3800 RAINIER AVE S	ICR and CSCSL	Petroleum, non-halogenated solvents, halogenated organic compounds and metals	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL: Groundwater and soil (confirmed) contaminated by petroleum products (confirmed), non-halogenated solvents (confirmed), halogenated organic compounds (suspected), and EPA priority pollutants - metals and cyanide (suspected); both entered 4-28-94. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, final cleanup report received 1-22-96. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-12-93. ICR #3: Soil contaminated by petroleum products, final cleanup report received 3-18-94. ICR #4: Soil contaminated by petroleum products, interim cleanup report received 3-18-94. ICR #5: Soil contaminated by petroleum products, final cleanup report received 12-5-94.
251	3801 E MARGINAL WAY S, 'ASH GROVE CEMENT COMPANY, 'ASH GROVE CEMENT WEST INC	3801 E MARGINAL WAY S	FIFRA / TSCA Tracking System, ICR, CSCSL (NFA), CERCLIS (NFA), and HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing	NR	NR	Hanford CS	CSCSL NFA (7-10-98) listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given.
252	SEATTLE CITY LIGHT 4TH AVE S	3814 4TH AVE S	ICR and CSCSL	Petroleum and metals/cyanide	Soil and Groundwater	Lander and Hanford CS	CSCSL: Soil and groundwater (both confirmed) contaminated by petroleum products (confirmed) and EPA priority pollutants - metals and cyanide (confirmed); both entered 4-2-01.
253	LONGS DRUG STORE 445, 'RAINIER VALLEY SQUARE	3820 RAINIER AVE S	CSCSL (NFA) and ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL NFA (4-2-96) listed, NFA Type: NFA after assessment, IRAP, VCP; no further information given 2 - ICR #1 Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-19-96. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-22-96. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-25-95. ICR #4: Soil contaminated by petroleum products, interim cleanup report received 6-9-94. ICR #5: Soil contaminated by petroleum products, final cleanup report received 3-14-96. ICR #6: Soil contaminated by petroleum products, final cleanup report received 1-22-96. ICR #7: Soil contaminated by petroleum products, interim cleanup report received 10-25-95. ICR #8: Soil contaminated by petroleum products, final cleanup report received 1-19-96. ICR #9: Soil contaminated by petroleum products, interim cleanup report received 6-9-94.
254	CASCADE COMMERCIAL COMPANY	3825 1ST AVE S	LUST and UST	NR	Soil	Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 4-10-00. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
255	RODDA PAINT 4TH AVE, 'WALTS RADIATOR & MUFFLER 4TH AVE	3838 4TH AVE S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 4-3-95. LUST #2: Soil contaminated, reported cleaned up, release status date 7-6-95. 2 - ICR: Soil contaminated by petroleum products, final cleanup report received 4-2-95
256	RESIDENCE	3839 46TH AVE. S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, final cleanup report received 5-4-94.
258	COLORADO ST FACILITY RAINIER PETRO, 'MC TERMINALS	40 S SPOKANE ST	ICR and CSCSL	Base/acid, halogenated organic compounds and PAHs	Soil and Groundwater	Hanford CS	1 - CSCSL: Groundwater (confirmed) and soil (suspected) contaminated by base/neutral/acid organics (both suspected), halogenated organic compounds (confirmed in groundwater, suspected in soil), polynuclear aromatic hydrocarbons (PAH)(both suspected); both entered 10-24-91. 2 - ICR: Groundwater contaminated by conventional organic contaminants, interim cleanup report received 8-19-91.
259	GARFIELD HIGH SCHOOL, 'SEATTLE SCHOOL DIST 1 GARFIELD HS	400 23 AV	FIFRA / TSCA Tracking System and HIST FTTS	NR	NR	Lander and Hanford CS	No detail provided
260	UNOCAL 5473	401 RAINIER AVE S	VCP, Institutional Control Site List, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed), entered 4-7-99. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-22-98. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-19-98. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-4-99. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 9-11-98. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-28-99. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-22-00. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-1-00. ICR #8: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-2-99. ICR #9: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-29-99. ICR #10: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-28-96. ICR #11: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-18-95. ICR #12: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-18-96. ICR #13: Groundwater and soil contaminated by petroleum products, interim cleanup report received date unknown. ICR #14: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-24-92. ICR #15: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-26-93. ICR #16: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-26-95. ICR #17: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-31-92. ICR #18: Groundwater and soil contaminated by petroleum products, interim cleanup report received 11-7-96. 2 VCPs in progress. 2 - LUST #1: Groundwater contaminated, cleanup started, release status date 3-24-93. LUST #2: Groundwater contaminated, monitoring, release status date 7-19-96. LUST #3: Soil contaminated, cleanup started, release status date 3-24-93. LUST #4: Soil contaminated, monitoring, release status date 9-24-90.
261	4058 RAINIER AVE S., 'DARIGOLD, 'WESTFARM FOODS SEATTLE, 'PENSKO TRUCK LEASING CO LP	4058 RAINIER AVE S	FIFRA / TSCA Tracking System, ICR, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Groundwater contaminated, cleanup started, release status date 6-1-95. ICR #1: Soil contaminated by petroleum products, interim cleanup report received 11-2-98. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 3-27-91.
262	JERGENS PAINTING, 'TANIGUCHI PROPERTY	415 18TH AVE S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 12-30-08. LUST #2: Soil contaminated, cleanup started, release status date 5-21-95.
263	BARRETT PROPERTY	416 RAINIER AVE S	CSCSL (NFA), VCP, and ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	CSCSL NFA and VCP (both 3-24-99) both listed, NFA Type: NFA after assessment, IRAP, or VCP. ICR #1: Groundwater and soil contaminated by petroleum products, final cleanup report received 11-4-98. ICR #2: Groundwater and soil contaminated by petroleum products, report received 11-4-98. ICR #3: Groundwater and soil contaminated by petroleum products, final cleanup report received 3-23-99. ICR #4: Groundwater and soil contaminated by petroleum products, final cleanup report received 11-4-98.
264	KANE PROPERTIES LLC	4208 RAINIER AVE S	CSCSL	Halogenated Organic Compounds	Soil and Suspected Groundwater	Lander and Hanford CS	CSCSL: Soil (confirmed) and groundwater (suspected) contaminated by halogenated organic compounds (confirmed for soil, suspected for groundwater), both entered 5-16-01.
270	44 SOUTH HANFORD	44 SOUTH HANFORD	HMRS	See Detailed Excerpts	NR	Hanford CS	1 - HMIRS: 30 gallons of methanol reported spilled on 6-21-01. 2 - HMIRS: 250 pounds of aluminum smelt by-product reported spilled on 3-26-03. 3 - HMIRS: .125 gallons of denatured alcohol reported spilled on 2-14-95. 4 - HMIRS: 2 gallons of methanol reported spilled on 7-6-01. 5 - HMIRS: Crude sulfate turpen vapor reported 7-14-02. 6 - HMIRS: 100 pounds of aluminum smelt by-product reported spilled on 3-26-03.
271	HARBORVIEW MENTAL HEALTH SERVICES	440 9TH AVENUE	PCB Activity Database	NR	NR	Lander and Hanford CS	No detail provided
272	JIMS AUTO REPAIR	4434 RAINIER AVE S	CSCSL, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 7-13-05. LUST #2: Soil contaminated, cleanup started, release status date 6-19-00. 2 - CSCSL: Soil (confirmed) contaminated by petroleum products (confirmed), entered on 7-13-05.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
273	USVA MEDICAL CTR	4435 BEACON AVE S	FIFRA / TSCA Tracking System and HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing	NR	NR	Lander and Hanford CS	No detail provided
274	NELSON IRON WORKS, 'IRISH FOUNDRY	45 S SPOKANE ST	CSCSL (NFA), Brownfields Listing (2), and ICR	Petroleum	Soil and Groundwater	Hanford CS	CSCSL NFA and VCP (both 3-19-04) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-10-94. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 9-23-91.
275	WA DOT SEATTLE S SPOKANE ST, 'WSDOT - SPOKANE ST. MAINTENANCE	450 S SPOKANE ST	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95. 2 - ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-18-94
277	SEATTLE HOUSING AUTHORITY MLK WY	4561 MARTIN LUTHER KING JR WY S	Brownfields Site List and CSCSL	Petroleum, non-halogenated solvents, and halogenated	Surface water and Groundwater	Lander and Hanford CS	CSCSL: Surface water and groundwater (both confirmed) contaminated by petroleum products (both confirmed), non-halogenated solvents (both confirmed), and halogenated organic compounds (confirmed in surface water, suspected in groundwater); both entered 6-5-07.
279	CLAYTON VW REPAIR	4709 MARTIN LUTHER KING JR WAY S	VCP, CSCSL, LUST, and UST	Petroleum, Arsenic, and PAH(s)	Soil, Groundwater, and Suspected Air and Surface Water	Lander and Hanford CS	1 - 3 VCPs in progress 2 - CSCSL: Soil (confirmed) contaminated by petroleum products (confirmed), arsenic code (confirmed), and polynuclear aromatic hydrocarbons (PAH)(confirmed); Surface water and air (both suspected) contaminated by petroleum products (suspected); all three entered on 3-5-91. 3 - LUST #1: Groundwater contaminated, cleanup started, release status date 5-21-95. LUST #2: Soil contaminated, cleanup started, release status date 5-21-95.
280	RESIDENTIAL UST	4729 51ST AVE. S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, final cleanup report received 3-23-94
284	SEATTLE CITY LIGHT SOUTH SUBSTATION	4TH AVE. S. / SPOKANE ST.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR #1: Soil contaminated by petroleum products, interim cleanup report received 8-3-90. ICR #2: Soil contaminated by total petroleum hydrocarbons, interim cleanup report received date unknown. ICR #3: Soil contaminated by petroleum products, report received 5-7-90.
285	500 17TH, 'SWEDISH MEDICAL CENTER PROVIDENCE CAMPUS, 'HOPE HEART INSTITUTE THE	500 17TH AVE RM (475D)	CSCSL (NFA), VCP, ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, reported cleaned up, release status date 4-5-00. 2 - CSCSL NFA (5-22-06) and VCP (5-22-06) both listed, no further information given 3 - ICR: Soil contaminated by petroleum products, final cleanup report received 12-30-99
287	5201 RAINIER LLC	5201 RAINIER AVE S	CSCSL (NFA)	NR	NR	Lander and Hanford CS	CSCSL NFA (3-21-08) listed, NFA Type: NFA after assessment, IRAP, or VCP
289	DAMASCUS BAPTIST CHURCH	5237 RAINIER AVE S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST: Soil contaminated, cleanup started, release status date 10-27-93.
292	DAMASCUS BAPTIST CHURCH	5261 RAINIER AVE. S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, interim cleanup report received 12-10-93.
294	MOSS G MILAN PROPERTY	537 W SPOKANE ST	VCP and CSCSL	metals and Cyanide	Groundwater	Lander and Hanford CS	1 - 1 VCP in progress 2 - CSCSL: Groundwater (confirmed) contaminated by EPA priority pollutants - metals and cyanide (confirmed), entered on 12-20-05
295	MILLER RESIDENCE	5502 S FERDINAND ST	CSCSL (NFA), VCP, LUST, and UST	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 3-20-02) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given
296	RUDY HANSON, 'RUDYS SHELL SERVICE	5520 RAINIER AVE S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST: Soil contaminated, cleanup started, release status date 9-27-99
297	SEATTLE UNIVERSITY AKA BLUE WHALE, 'BLUE WHALE/SEATTLE UNIVERSITY	610 13TH AVE	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil affected, reported cleaned up, release status date 8-21-91. LUST #2: Soil affected, cleanup started, release status date 6-26-91. 2 - ICR #1: Soil affected by petroleum products, final cleanup report received 8-12-91. ICR #2: Soil affected by petroleum products, interim cleanup report received 8-21-91.
298	METAL LAUNDRY INCORPORATED	614 12TH	VCP, CERCLIS (NFA), and CSCSL	Non-halogenated, halogenated organics and metals/cyanide	Soil and Groundwater	Lander and Hanford CS	CSCSL: Groundwater (confirmed) contaminated by non-halogenated solvents (confirmed), halogenated organic compounds (confirmed), and EPA priority pollutants - metals and cyanides (suspected), entered 3-1-88. Soil (confirmed) contaminated by petroleum products (confirmed), non-halogenated solvents (confirmed), and EPA priority pollutants - metals and cyanides (confirmed), entered on 3-1-88. 2 VCPs in progress.
299	TAYLOR EDWARDS SEATTLE	615 HOLGATE ST	ICR	Petroleum	Soil	Lander and Hanford CS, Lander West SB	ICR: Soil contaminated by petroleum products, final cleanup report received 8-10-90
300	ALASKAN COPPER & BRASS CO	628 S HANFORD	FIFRA / TSCA Tracking System	NR	NR	Lander and Hanford CS, Lander West SB	No detail provided
301	SOUTHERN ALASKA FORWARDERS	646 S HOLGATE ST	CSCSL (NFA), VCP, and UST	NR	NR	Lander and Hanford CS, Lander West SB	CSCSL NFA and VCP (both 2-23-09) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given
302	PAPER FIBERS RECYCLING CO, 'RABANCO RECYCLING HIGH GRADE	66 S HANFORD	FIFRA / TSCA Tracking System and HIST FTTS	NR	NR	Lander and Hanford CS	No detail provided
303	ARCO 5445, 'BP ARCO AM/PM	665 23RD AVE	LUST and UST	NR	Soil and Groundwater	Lander and Hanford CS	LUST #1: Ground water contaminated , awaiting cleanup, release status date 9-7-05. LUST #2: Soil contaminated, awaiting cleanup, release status date 9-7-05.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
305	SHELL STATION 121499, 'SHELL #47481/TEXACO #121499	700 12TH AVE	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL: Groundwater and soil (both confirmed) affected by petroleum products (confirmed), entered 12-23-08 2 - ICR: Groundwater and soil affected by petroleum products, interim report received 10-4-99. 3 - ICR: Groundwater and soil affected by petroleum products, interim report received 5-15-92 4 - ICR: Groundwater affected by petroleum products, interim report received 7-11-94. 5 - ICR: Groundwater and soil affected by petroleum products, interim report received 10-16-95. 6 - ICR: Groundwater and soil affected by petroleum products, interim report (Monitoring - August 2000) received 11-8-00 7 - ICR: Groundwater and soil affected by petroleum products, interim report (Semiannual Monitoring - January 2001) received 4-25-01. 8 - ICR: Groundwater and soil affected by petroleum products, interim report (Sampling July 2001) received 12-4-01. 9 - ICR: Groundwater and soil affected by petroleum products, interim report received 5-28-93. 10 - ICR: Groundwater and soil affected by petroleum products, interim report received 12-6-93. 11 - ICR: Groundwater affected by petroleum products, interim report received 10-20-94. 12 - ICR: Groundwater affected by petroleum products, interim report received 4-5-95. 13 - ICR: Groundwater affected by petroleum products, interim report received 5-9-95. 14 - ICR: Groundwater affected by petroleum products, interim report received 5-20-95. 15 - ICR: Groundwater and soil affected by petroleum products, interim report received 4-22-97. 16 - ICR: Groundwater and soil affected by petroleum products, interim report (First Quarter Ground Water Monitoring 2002) received 6-21-02. 17 - ICR: Groundwater and soil affected by petroleum products, interim report received 4-2-98. 18 - ICR: Groundwater and soil affected by petroleum products, interim report received 5-26-00. 19 - ICR: Groundwater affected by petroleum products, interim report received 11-6-91. 20 - ICR: Groundwater affected by petroleum products, interim report received 12-1-92. 21 - LUST #1: Groundwater affected, monitoring, release status date 10-1-95. LUST #2: Soil affected, monitoring, release status date 10-1-95. LUST #3: Soil affected, monitoring, release status date 4-18-97. LUST #4: Soil affected, cleanup started, release status date 12-27-90. LUST #5: Groundwater affected, monitoring, release status date 4-18-97. LUST #6: Groundwater affected, cleanup started, release status date 12-27-90.
306	CITY OF SEATTLE, 'SEATTLE CITY HEALTH DEPT, 'CHARLES STREET SITE WEST	705 CHARLES ST. E.	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	LUST #1: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95. ICR #1: Soil contaminated by petroleum products, interim cleanup report (Final - UST Removal and Soil/GW Investigation) received 6-29-93. ICR #2: Soil contaminated by petroleum products, interim cleanup report (Appendices - UST Removal and Soil/GW Investigation) received 6-29-93.
309	TEXACO #63232 1489	719 RAINIER AVE. S.	ICR	Petroleum	Groundwater	Lander and Hanford CS	ICR: Groundwater contaminated by petroleum products, interim cleanup report received 5-22-95.
310	GRAY LINE OF SEATTLE	720 S FOREST ST	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	LUST #1: Soil contaminated, cleanup started, release status date 9-28-95. LUST #2: Groundwater contaminated, cleanup started, release status date 9-28-95. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-14-90. ICR #2: Groundwater and soil contaminated, final cleanup report received 4-11-91.
311	UNK, '12TH & COLUMBIA SITE	729 12TH AVE	CSCSL (NFA) and VCP	NR	NR	Lander and Hanford CS	CSCSL NFA (8-8-02) and VCP (8-8-02) listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given.
312	SWEDISH HOSPITAL MEDICAL CTR	747 BROADWAY	LUST and UST	Soil	NR	Lander and Hanford CS	LUST #1: Soil contaminated, cleanup started, release status date 2-23-93. LUST #2: Soil contaminated, reported cleaned up, release status date 6-1-95. LUST #3: Soil contaminated, cleanup started, release status date 12-24-91. LUST #4: Soil contaminated, reported cleaned up, release status date 6-1-95.
314	SEARS ROEBUCK & CO 1009	76 S LANDER ST	FIFRA / TSCA Tracking System, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, CSCSL, LUST and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed); both entered 3-15-07. LUST #1: Soil contaminated, awaiting cleanup, release status date 6-1-95. LUST #2: Groundwater contaminated, awaiting cleanup, release status date 6-1-95.
315	MARKEY MACHINERY CO INC	79 S HORTON ST	CSCSL (NFA) and VCP	NR	NR	Hanford CS	CSCSL NFA and VCP (both 1-22-08) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given
317	FOOD SERVICE INTERNATIONAL	801 S HOLGATE	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 11-20-91. LUST #2: Soil contaminated, reported cleaned up, release status date 6-1-95. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-13-92. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-13-93.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
319	MODEL & INSTRUMENT DEVELOPMENT, 'SIGNAL EQUIPMENT INC.	836 POPLAR PL S	CERCLIS (NFA), ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - ICR #1: Soil contaminated by petroleum products, final cleanup report received 5-22-94. ICR #2: Soil contaminated by petroleum products, final cleanup report received 9-11-92. 2 - ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-10-92. 3 - CSCSL: Soil (confirmed) and groundwater (suspected) contaminated by petroleum products (confirmed in soil, suspected in groundwater), both entered 8-1-05. 4 - LUST #1: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95.
321	THE RECYCLING DEPOT INC	851 RAINIER AVE S	Solid Waste Facility Database	NR	NR	Lander and Hanford CS	No detail provided
322	SHELL RAINIER AVE S SEATTLE, 'SHELL STATION 121607	852 RAINIER AVE S	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 4-11-91. LUST #2: Groundwater contaminated, monitoring, release status date 9-8-94. LUST #3: Groundwater contaminated, cleanup started, release status date 4-11-91. LUST #4: Soil contaminated, monitoring, release status date 9-8-94. 2 - 2 VCPs in progress 3 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed for both) and metals - other non-priority pollutant metals (confirmed for groundwater, below cleanup level for soil), both entered 2-17-09. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-30-98. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 7-31-98. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-27-98. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-11-99. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-6-99. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-26-00. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-15-91. ICR #8: Groundwater and soil contaminated by petroleum products, interim cleanup report received date unknown. ICR #9: Groundwater and soil contaminated by petroleum products, interim cleanup report received 11-24-93. ICR #10: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-20-95. ICR #11: Groundwater contaminated by petroleum products, interim cleanup report received 4-24-95. ICR #12: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-30-95. ICR #13: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-16-95. ICR #14: Groundwater and soil contaminated by petroleum products, interim cleanup report (Monitoring - January 2001) received 3-20-01. ICR #15: Groundwater contaminated by petroleum products, interim cleanup report received 1-17-96. ICR #16: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-23-96. ICR #17: Groundwater and soil contaminated by petroleum products, interim cleanup report (Sampling - August 2001) received 12-4-01. ICR #18: Groundwater and soil contaminated by petroleum products, interim cleanup report (Monitoring - September 2000) received 11-13-00. ICR #19: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-16-96. ICR #20: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-21-97. ICR #21: Groundwater and soil contaminated by petroleum products, interim cleanup report (Fourth Quarter Ground Water Monitoring 2002) received 12-11-02. ICR #22: Groundwater and soil contaminated by petroleum products, interim cleanup report (Ground Water Monitoring - March 2002) received 6-21-02.
323	EMERALD CITY DISPOSAL MASSACHUSETTS, 'COAL CREEK DEVELOPMENT LANDFILL, 'US COAST GUARD PIER 35	9 S MASSACHUSETTS	ICP, CSCSL, LUST, and UST	Petroleum and halogenated organic compounds,	Surface water and Soil	B-25 SB	1 - CSCSL: Surface water (confirmed) contaminated by petroleum products (below cleanup level) and halogenated organic compounds (confirmed); soil (confirmed) contaminated by petroleum products (confirmed) and halogenated organic compounds (below cleanup level); both entered 11-9-04 2 - LUST: Soil contaminated, cleanup started, release status date 10-5-98 3 - ICR: Soil contaminated by petroleum products, interim cleanup report received 10-7-08.
324	'CANELLA INC	'901 HIAWATHA PL S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 1-2-08. LUST #2: Soil contaminated, cleanup started, release status date 12-21-07.
326	HOSPITAL CORP OF AMERICA 904, 'SHEPARD AMBULANCE	904 12TH AVE	CSCSL (NFA), ICR, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL NFA dated 12-1-95, but no further information given. 2 - ICR #1: Soil contaminated by petroleum products, final cleanup report received 8-7-95. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-2-94.
327	MOTOR FREIGHT SERVICES INC	916 COLLEGE ST	CSCSL, VCP, and ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - CSCSL NFA and VCP (both 5-14-99) both listed, NFA Type: NFA after assessment, IRAP, or VCP 2 - ICR #1: Groundwater and soil contaminated by petroleum products and halogenated solvents, interim cleanup report received 7-15-98. ICR #2: Groundwater and soil contaminated by halogenated organic compounds and petroleum products, final cleanup report received 4-22-99.
329	MOSS ALLEY MOTORS	932 12TH AVE	CSCSL (NFA) and ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL NFA (12-1-95) listed, no further information given 2 - Groundwater and soil contaminated by petroleum products, final cleanup report received 8-7-95
331	SEATTLE UNIVERSITY	BROADWAY & E MADISON	FIFRA / TSCA Tracking System, ICR, and HIST	Petroleum	Soil and Groundwater	Lander and Hanford CS	ICR #1: Groundwater and soil contaminated by petroleum products, final cleanup report received 10-5-98. ICR #2: Soil contaminated by petroleum products, final cleanup report received 5-21-93.

**Table G-1
Listed Sites**

Note: Formatted for ledger-size printing

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
333	GENESEE LANDFILL	GENESEE ST / 43RD AVE S	CSCSL	Pesticides, halogenated organic compounds,	Air, and Suspected Groundwater, Surface Water and Soil	Lander and Hanford CS	CSCSL: Groundwater, surface water, and soil (all suspected) contaminated by pesticides (suspected), halogenated organic compounds (suspected), EPA priority pollutants - metals and cyanide (suspected), and polynuclear aromatic hydrocarbons (PAH)(suspected); air (confirmed) contaminated by inorganic conventional contaminants; all four entered on 3-1-88.
334	SEATTLE CITY ROW HOLGATE & 3RD	HOLGATE AVE / 3RD AVE S	CSCSL	Arsenic and metals/cyanide	Soil and Suspected Groundwater	Lander and Hanford CS, Lander West SB	CSCSL: Soil (confirmed) contaminated by arsenic code (confirmed) and EPA priority pollutants - metals and cyanide (confirmed); groundwater (suspected) contaminated by arsenic code (suspected) and EPA priority pollutants - metals and cyanide (suspected); both entered 9-1-04
335	WA DOT I-90 & RAINIER AVE	I-90 / RAINIER AVE S	CSCSL (NFA) and VCP	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 5-21-95. LUST #2: Soil contaminated, cleanup started, release status date 1-25-89.
337	SWEDISH HOSPITAL GAS STATIONS	MADISON MINOR MARION BOREN	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 5-21-91. LUST #2: Soil contaminated, cleanup started, release status date 6-26-91.
338	SEATTLE, CY OF, RAINIER PLAYFIELD	OREGON ST S & 38TH	Brownfield Listing	NR	NR	Lander and Hanford CS	No detail provided
341	RAINIER COURT	RAINIER AVE S	Brownfeild Listing, VCP, and CSCSL	Pesticides, Petroleum, metals/cyanide, PCBs, and PAHs	Soil and Groundwater	Lander and Hanford CS	1 - 2 VCPs in progress 2 - CSCSL: Groundwater and soil (both confirmed) contaminated by pesticides (below cleanup level), petroleum products (confirmed), EPA priority pollutants - metals and cyanide (confirmed), polychlorinated biphenyls (PCBs)(below cleanup level), polynuclear aromatic hydrocarbons (PAHs)(confirmed); both entered 6-19-01.
344	SEATTLE CITY ROW S HORTON & OCCIDENTAL S	S HORTON ST /	CSCSL	Petroleum	Soil	Hanford CS	CSCSL: (Soil confirmed) contaminated by petroleum products (confirmed), entered on 1-1-07.
345	WA DOT SEATTLE I90 TIME OIL	S NORMAN ST /	CSCSL (NFA) and VCP	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 7-19-00) both listed, NFA Type: NFA after assessment, IRAP, or VCP, no further information given

Notes:

CS = Combined Sewer

CSCSL = Confirmed and Suspected Contaminated Site List

ICR = Independent Cleanup Report

LUST = Leaking Underground Storage Tank Database

NFA = No Further Action

NR = Not Reported

SB = Stormwater Basin

UST = Underground Storage Tank Database

VCP = Voluntary Cleanup Program

All sites were listed on one or more of the following databases: Corrective Action Report, FIFRA / TSCA Tracking System, CSCSL - No Further Action, Brownfields Site List, Voluntary Site Cleanup Program Sites, PCB Activity Database, Institutional Control Site List, a listing of brownfield sites, CERCLIS, CERCLIS (no further action), Independent Cleanup Reports, Hazardous Material Reporting System, EDR Proprietary Manufactured Gas Plants, ICIS Integrated Compliance Information System, HIST FTTS FIFRA / TSCA Tracking System Administrative Case Listing, Confirmed and Suspected Contaminated List, Leaking Underground Storage Tank, Solid Waste Facility Database, Material Licensing Tracking System, Hazardous Sites List, Underground Storage Tank Database, RCRA Administrative Action Tracking System