



## Appendix G –

# Listed Site Database Search Results for East Waterway Associated Drainage Basins

---

### Introduction:

Sites listed in federal and state environmental databases were queried to provide supplemental information potentially useful during source tracing activities within the East Waterway (EW) watersheds. The database queries were conducted by Environmental Data Resources in December 2009. The database information is not necessary to characterize current stormwater or combined sewer overflow (CSO) discharges to the EW, because these discharges have been characterized directly, including any potential contributions from cleanup sites located within the storm drain (SD) or CSO basins.

### Text References:

This appendix was referenced in the following sections of the *East Waterway Operable Unit Revised Draft Supplemental Remedial Investigation Report – Section 9: Source and Pathway Characterization*:

- Section 9.3.6.1 – Ecology Toxics Cleanup Program
- Section 9.4.4.3 – Groundwater Pathway and Inland Cleanup Sites

### Map Reference:

This appendix was referenced in the following map of the *East Waterway Operable Unit Revised Draft Supplemental Remedial Investigation Report – Section 9: Source and Pathway Characterization*:

- Map 9-7 – Listed Sites within EW Combined Sewer and Inland Storm Drainage Basins























**Table G-1  
Listed Sites**

*Note: Formatted for ledger-size printing*

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
186	RAINIER BREWERY CO, 'G HEILEMAN BREWING CO	3100 AIRPORT WAY S	FIFRA / TSCA Tracking System, ICR, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, monitoring, release status date 5-18-00. LUST #3: Groundwater, cleanup started, release status date 6-1-95. LUST #4: Groundwater contaminated, monitoring, release status date 5-18-00. 2 - CSCSL: Soil (remediated) contaminated by petroleum products (remediated); Groundwater (confirmed) contaminated by petroleum products (confirmed); both entered 1-21-00. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-21-00. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-18-00. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-16-00. ICR #4: Soil contaminated by petroleum products, interim cleanup report received 11-29-90. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report (Remedial Investigation/Feasibility Study/Cleanup Action Plan) received 1-15-02.
187	3A INDUSTRIES INC	3101 MARTIN LUTHER KING JR WAY S	VCP and CSCSL	Non-halogenated, halogenated organics and Petroleum	Soil and Groundwater	Lander and Hanford CS	CSCSL: Groundwater (confirmed) contaminated by non halogenated solvents (below cleanup level), and halogenated organic compounds (confirmed); Soil (below cleanup level) contaminated by petroleum products (suspected), non-halogenated solvents (below cleanup level), and halogenated organic compounds (below cleanup level); both entered 8-17-04. 2 VCPs in progress.
188	SUN PROPERTY	3114 12TH AVE S	CSCSL (NFA) and CSCSL	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 12-5-01) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given.
192	ANDYS DINER INC	3201 4TH AVE S	LUST and UST	NR	Soil and Groundwater	Lander and Hanford CS	LUST #1: Groundwater contaminated, cleanup started, release status date 3-24-93. LUST #2: Soil contaminated, cleanup started, release status date 3-24-93.
194	SCALZO COMPANY	3211 AIRPORT WAY S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, interim cleanup report received 2-16-94
195	PACIFIC EXPRESS	3215 4TH AVE S	CSCSL, LUST, and UST	Petroleum and non-halogenated solvents	Soil, Groundwater, and Suspected Air	Lander and Hanford CS	1 - CSCSL: Air (suspected), groundwater (confirmed), soil (confirmed) contaminated by petroleum products (suspected in air, confirmed in groundwater in groundwater and soil) and non-halogenated solvents (suspected in air, confirmed in groundwater in groundwater and soil); all three entered 2-9-04. 2 - LUST #1: Groundwater contaminated, awaiting cleanup, release status date 5-1-98. LUST #2: Soil contaminated, cleanup started, release status date 1-21-00. LUST #3: Soil contaminated, awaiting cleanup, release status date 5-1-98. LUST #4: Groundwater contaminated, cleanup started, release status date 1-21-00.
196	BP/SOUTHCENTER OIL/PACIFIC EXPRESS	3215 4TH AVE. S.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	ICR #1: Soil contaminated by petroleum products, interim cleanup report received 7-31-98. ICR #2: Groundwater contaminated by petroleum products, interim cleanup report received 8-9-99. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-27-99. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-2-99. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 9-10-98. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 7-31-98. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-17-00. ICR #8: Groundwater and soil contaminated by petroleum products, interim cleanup report (Sampling - April 2000) received 5-30-00. ICR #9: Groundwater and soil contaminated by petroleum products, interim cleanup report (Quarterly Status) received 6-28-01. ICR #10: Groundwater and soil contaminated by petroleum products, interim cleanup report (Results of Third Quarter 2000 Ground Water Monitoring) received 11-27-00. ICR #11: Groundwater contaminated by metals, total petroleum hydrocarbons, 42, interim cleanup report (Results of Fourth Quarter 2001 Ground Water Monitoring) received 1-29-02. ICR #12: Groundwater and soil contaminated by petroleum products, interim cleanup report (Second Quarter 2000 Ground Water Monitoring) received 8-21-00. ICR #13: Groundwater and soil contaminated by petroleum products, interim cleanup report (Monitoring - October 1999) received 11-30-99. ICR #14: Groundwater and soil contaminated by petroleum products, interim cleanup report (July 2002 Ground Water Monitoring Report - Third Quarter) received 9-30-02.
197	SEATTLE BEST CLEANERS, 'BEACON MARKET	3219 MARTIN LUTHER KING JR WAY S	ICR, CSCSL, LUST, and UST	Halogenated Organic Compounds	Soil	Lander and Hanford CS	1 - CSCSL: Soil (confirmed) contaminated by halogenated organic compounds (confirmed), entered 2-16-09. LUST: Soil contaminated, awaiting cleanup, release status date 10-27-08. 2 - Soil contaminated by petroleum products, interim cleanup report received 11-12-92.
198	ALASKA COPPER & BRASS	3223 6TH AVE S	CSCSL	Corrosive Wastes, metals and Cyanide,	Suspected Soil and Groundwater	Lander and Hanford CS	CSCSL: Groundwater and soil (suspected) contaminated by reactive wastes (suspected), corrosive wastes (suspected), EPA priority pollutants - metals and cyanide (suspected), inorganic conventional contaminants (suspected); both entered 3-1-88.
199	SEATTLE FIRE STATION 14	3224 4TH AVE S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST: Soil contaminated, cleanup started, release status date 2-14-00. 2 - ICR: Soil contaminated by petroleum products, interim cleanup report (Site Characterization Report) received 5-21-02
203	KING CO HARBORVIEW MEDICAL CTR	325 9TH AVE		Petroleum	Soil	Lander and Hanford CS	ICR #1: Soil affected by petroleum products, interim report received 9-4-91. ICR #2: Soil affected by petroleum products, interim report received 4-14-92.
204	HARBORVIEW MEDICAL CENTER	325 NINTH AVENUE	LUST	NR	Soil	Lander and Hanford CS	LUST #1: Soil affected, cleanup started, release status date 4-3-91. LUST #2: Soil affected, reported cleaned up, release status date 4-20-00.

**Table G-1  
Listed Sites**

*Note: Formatted for ledger-size printing*

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
205	ROADWAY EXPRESS INC	3300 6TH AVE S	HMRS	See Detailed Excerpts	NR	Lander and Hanford CS	1 - HMIRS: .02343750 gallons of compound cleaning liquid reported spilled. 2 - HMIRS: .0625 gallons of hydrogen peroxide (20-40%) reported spilled 10-23-92 3 - HMIRS: 1 gallon of iodate solution reported spilled on 7-31-94 4 - HMIRS: .5 gallons of adhesives reported spilled on 8-31-94 5 - HMIRS: 10 gallons of isopropanol reported spilled on 10-5-97 6 - HMIRS: .5 gallons of film developer reported spilled on 8-28-98. 7 - HMIRS: .046875 gallons of toxic liquids cor organic reported spilled on 7-16-96 8 - HMIRS: .125 pounds of calcium hypochlorite dry reported spilled on 7-24-97 9 - HMIRS: .25 gallons of methanol reported spilled on 10-16-92 10 - HMIRS: 1 gallon of resin solution reported spilled on 10-28-92 11 - HMIRS: .03125 gallons of alkylamines N.O.S. CORROS reported spilled on 2-8-94 12 - HMIRS: 4 gallons of Targo wet or dry spo reported spilled on 3-20-94 13 - HMIRS: .125 gallons of corrosive liquids N.O.S. reported spilled on 1-26-95 14 - HMIRS: 5 gallons of hydrocarbons liquid NOS reported spilled on 10-5-96 15 - HMIRS: 2 gallons of aquathall k reported spilled on 6-2-90 16 - HMIRS: 17 - HMIRS: 3 gallons of ink printers flammable reported spilled on 3-20-99 18 - HMIRS: 10 gallons of printing ink flammable reported spilled on 5-4-98 19 - HMIRS: .5 gallons of resing solution reported spilled on 1-29-02 20 - HMIRS: 5 pounds of alkyl sulfonic acid solids reported spilled on 9-21-98 21 - HMIRS: 3 gallons of phosphoric acid reported spilled on 6-13-02 22 - HMIRS: .0078125 gallons of compressed gas NOS reported spilled on 9-9-97 23 - HMIRS: 2 gallons of adhesives reported spilled on 10-13-94 24 - HMIRS: Magnesium nitrate reported spilled on 8-24-00 25 - HMIRS: .05 gallons of 5-chloro-2-methyl-4-? reported spilled 6-11-02 26 - HMIRS: 1 gallon of aromatic ethanol reported spilled on 3-24-00 27 - HMIRS: 1 gallon of aromatic ethanol reported spilled on 3-24-00 28 - HMIRS: 1 gallon of adhesives reported spilled on 6-6-02
206	LOVSTEAD INDUSTRIES	3300 AIRPORT WY S	CSCSL (NFA)	NR	NR	Lander and Hanford CS	CSCSL NFA (9-10-91) listed, NFA Type: cleaned up under prior authority
209	BURGER KING SITE	3301 4TH AVE S	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 7-10-02. LUST #2: Soil contaminated, cleanup started, release status date 5-21-95. 2 - ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-11-90.
212	REI WOODWORKING (FORMER)	3314 4TH AVE. S.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	ICR #1: Groundwater and soil contaminated by petroleum products, final cleanup report received 5-20-96. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-15-96.
214	RESIDENTIAL UST	3328 CASCADIA AVE.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, final cleanup report received 12-27-93
215	CHUBBY AND TUBBY SITE	3333 RAINIER AVE S	Brownsfield Listing, CERCLIS (NFA), CSCSL, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - CSCSL: Soil (confirmed) contaminated by petroleum products (below cleanup level) and EPA priority pollutants - metals and cyanide (below cleanup level), entered on 9-30-08. 2 - LUST #1: Soil contaminated, reported cleaned up, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 6-12-91. ICR: Soil contaminated by petroleum products, final cleanup report received 2-11-92.
216	WALKER RESIDENCE	336 18TH AVE. E.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, final cleanup report received 2-3-93
217	AURORA CRANE CORP, TRANSPORT EQUIPMENT CO	3400 6TH AVE S	FIFRA / TSCA Tracking System, ICR, and UST	NR	NR	Lander and Hanford CS	No detail provided
219	ALASKA COPPER & BRASS	3405 6TH AVE. S.	ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 9-11-90.
222	PRESERVATIVE PAINT COMPANY	3410 AIRPORT WAY S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, interim cleanup report (Phase I Site Assessment) received 8-29-97.
223	NORTHWEST CASTINGS	3411 1ST AVE S	FIFRA / TSCA Tracking System, ICR, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, and ICIS	NR	NR	Hanford CS	No detail provided

**Table G-1  
Listed Sites**

*Note: Formatted for ledger-size printing*

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
224	ACME INTERCITY FREIGHT, 'PACKAGE SERVICE INC, 'COMMERCIAL PROPERTY	3414 2ND AVE S	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Surface water and Soil	Hanford CS	1 - CSCSL: Surface water (confirmed) contaminated by petroleum products (suspected), non-halogenated solvents (suspected), and metals - other non-priority pollutant metals (confirmed); Soil (confirmed) contaminated by petroleum products (confirmed) and non-halogenated solvents (suspected); entered on 4-27-96. 2 VCPs in progress. 2 - LUST: Soil contaminated, cleanup started, release status date 7-25-01. 3 - ICR: Soil contaminated by petroleum products, interim cleanup report (UST Closure Site Assessment) received 11-15-01.
225	SASAKI RESIDENCE	3417 18TH AVE S	CSCSL (NFA) and VCP	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 9-30-03) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given
226	ENTERPRISES NW	3422 1ST AVE S	VCP, CSCSL, and UST	Petroleum, metals and Cyanide, PCBs, and PAHs	Soil and Groundwater	Hanford CS	1 - 2 VCPs in progress 2 - CSCSL: Soil (confirmed) and groundwater (confirmed) contaminated by petroleum products (confirmed for soil, suspected for groundwater), EPA priority pollutants - metals and cyanide (only in soil, confirmed), polychlorinated biphenyls (PCBs)(confirmed for both), and polynuclear aromatic hydrocarbons (PAHs)(only for soil, confirmed); both entered on 1-1-07.
228	3433 4TH S PROPERTY, 'BUSINESS PRO COMPUTERS	3433 4TH AVE S	CSCSL (NFA), ICR, and LUST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 3-27-89. LUST #2: Groundwater contaminated, cleanup started, release status date 3-27-89. LUST #3: Soil contaminated, reported cleaned up, release status date 6-15-94. LUST #4: Groundwater contaminated, monitoring, release status date 5-21-95. LUST #5: Soil contaminated, monitoring, release status date 5-21-95. LUST #6: Groundwater contaminated, reported cleaned up, release status date 6-15-94. 2 - CSCSL NFA (11-9-94), NFA Type: Restrictive Covenant, Institutional Controls, no further information given 3 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-1-92. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-21-94.
229	ROADLINK TRANSPORTATION SOLUTIONS	3433 AIRPORT WAY S	PCB Activity Database	PCBs	NR	Lander and Hanford CS	No detail provided
230	CRAIN NW INC	3434 4TH AVE S	CSCSL (NFA), VCP, and UST	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 9-17-02) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information provided
231	PENSKE TRUCK LEASING CO LP, 'ROLLINS LEASING CORP	3443 1ST AVE S	ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Hanford CS	1 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed), both entered on 9-30-02. 2 - ICR: Groundwater and soil contaminated by petroleum products, final cleanup report received date unknown. 3 - LUST: Soil contaminated, cleanup started, release status date 1-17-91.

**Table G-1  
Listed Sites**

*Note: Formatted for ledger-size printing*

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
232	UNOCAL SS NO 5472	3460 1ST AVE S	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Hanford CS	1 - CSCSL: Soil (below cleanup level) and groundwater (confirmed) contaminated by petroleum products (soil - below cleanup level; groundwater - confirmed); both entered 10-23-98. 2 VCPs in progress. 2 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Groundwater contaminated, monitoring, release status date 6-2-95. LUST #3: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #4: Soil contaminated, monitoring, release status date 6-2-95. 3 - ICR #1: Groundwater and soil contaminated, interim cleanup report received date unknown. ICR #2: Groundwater and soil contaminated, interim cleanup report received 1-28-98. ICR #3: Groundwater and soil contaminated, interim cleanup report received 4-28-98. ICR #4: Groundwater and soil contaminated, interim cleanup report received 7-20-98. ICR #5: Groundwater and soil contaminated, interim cleanup report received 8-14-98. ICR #6: Groundwater and soil contaminated, interim cleanup report received 10-23-98. ICR #7: Groundwater and soil contaminated, interim cleanup report received 11-30-98. ICR #8: Groundwater and soil contaminated, interim cleanup report received 1-15-99. ICR #9: Groundwater and soil contaminated, interim cleanup report received 12-3-98. ICR #10: Groundwater and soil contaminated, interim cleanup report (Monitoring - March 2000) received 6-12-00. ICR #11: Groundwater and soil contaminated, interim cleanup report (Remediation Performance - 11/99 through 7/00) received 8-10-00. ICR #12: Groundwater and soil contaminated, interim cleanup report received 2-2-00. ICR #13: Groundwater and soil contaminated, interim cleanup report received 5-22-92. ICR #14: Groundwater and soil contaminated, interim cleanup report received 3-12-93. ICR #15: Groundwater and soil contaminated, interim cleanup report received 3-13-95. ICR #16: Groundwater and soil contaminated, interim cleanup report received 12-1-95. ICR #17: Groundwater and soil contaminated, interim cleanup report received 12-12-96. ICR #18: Groundwater and soil contaminated, interim cleanup report received 6-7-96. ICR #19: Groundwater and soil contaminated, interim cleanup report (Quarterly Monitoring - First Quarter 1999) received 7-14-99. ICR #20: Groundwater and soil contaminated, interim cleanup report (UST Removal June 1999) received 9-20-99. ICR #21: Groundwater and soil contaminated, interim cleanup report (Ground Water Monitoring - 4th Quarter 2000) received 1-16-01. ICR #22: Groundwater and soil contaminated, interim cleanup report (Third Quarter Ground Water Monitoring 2000) received 12-18-00. ICR #23: Groundwater and soil contaminated, interim cleanup report (Fourth Quarter Ground Water Monitoring 2001) received 1-22-02. ICR #24: Groundwater and soil contaminated, interim cleanup report received. ICR #25: Groundwater and soil contaminated, interim cleanup report (Third Quarter Ground Water Monitoring - August 2001) received 10-30-01. ICR #26: Groundwater and soil contaminated, interim cleanup report (Second Quarter Ground Water Monitoring - June 2001) received 10-30-01. ICR #27: Groundwater and soil contaminated, interim cleanup report (Third Quarter Ground Water Monitoring 2001) received 10-23-01. ICR #28: Groundwater and soil contaminated, interim cleanup report (Tosco Marketing Company Ground Water Monitoring Report) received 7-12-01. ICR #29: Groundwater and soil contaminated, interim cleanup report (Remedial System Quarterly Operation & Maintenance Report) received 6-19-01. ICR #30: Groundwater and soil contaminated, interim cleanup report (Ground Water Monitoring - Quarter 1 and Quarter 2, 2001) received 4-25-01. ICR #31: Groundwater and soil contaminated, interim cleanup report (Ground Water Monitoring - First Quarter 2001) received 1-9-01. ICR #32: Groundwater and soil contaminated, interim cleanup report (Ground Water Monitoring - Third Quarter 2000) received 3-28-97. ICR #33: Groundwater and soil contaminated, interim cleanup report received 9-13-00. ICR #34: Groundwater and soil contaminated, interim cleanup report (Ground Water Monitoring Report) received 3-4-02. ICR #35: Groundwater and soil contaminated, interim cleanup report (Third Quarter Ground Water Monitoring 2002) received 11-12-02.
236	ACKERLEY COMMUNICATIONS OF THE NW INC, 'CLEAR CHANNEL OUTDOOR	3601 6TH AVE S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, reported cleaned up, release status date 4-11-00.
237	SEATTLE PUBLIC UTILITIES BEACON HILL RES, 'SEATTLE FIRE STATION 13, 'BEACON RESERVOIR	3601 BEACON AVE S	ICR, LUST, and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, awaiting cleanup, release status date 2-16-00. LUST #2: Soil contaminated, cleanup started, release status date 2-16-00. LUST #3: Soil contaminated, reported cleaned up, release status date 8-2-02.
238	TIME STATION 234	3601 MARTIN LUTHER KING JR WAY	CSCSL (NFA) and UST	NR	NR	Lander and Hanford CS	CSCSL NFA (3-31-09) listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information listed
239	MOUNT BAKER BUILDING (THREE REPORTS)	3601 MCCLELLAN	CSCSL (NFA), VCP, ICR and UST	Petroleum	Soil	Lander and Hanford CS	1 - ICR #1: Soil contaminated by petroleum products, interim cleanup report received 1-30-97. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 1-1-94. Soil contaminated by petroleum products, final cleanup report received 11-26-96. 2 - CSCSL NFA (2-26-98), NFA Type: Restrictive Covenant, Institutional Controls
240	GENESEE SHELL & MINI MART, 'SHELL	3611 GENESEE ST S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 2-23-93. LUST #2: Soil contaminated, cleanup started, release status date 12-1-89 2 - ICR #1: Soil contaminated by petroleum products, final cleanup report received 9-28-92. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 9-28-92. ICR #3: Soil contaminated by petroleum products, interim cleanup report received 12-22-92. ICR #4: Soil contaminated by petroleum products, final cleanup report received 2-23-93.
241	RAINIER COURT PHASE IV (THE HOME OWNERSHIP PROJECT	3612-3656 34TH AVE. SOUTH	Brownfield Listing	NR	NR	Lander and Hanford CS	No detail provided



**Table G-1  
Listed Sites**

*Note: Formatted for ledger-size printing*

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
242	SEATTLE CITY LIGHT MRWF, 'SEATTLE CITY LIGHT (FIVE REPORTS)	3613 4TH AV S	FIFRA / TSCA Tracking System, ICR, PCB Activity Database, CERCLIS (NFA), ICR, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, LUST, Solid Waste Facility Database, and UST	Petroleum, Dioxin, and PCBs	Soil, Groundwater and Suspected Air	Lander and Hanford CS	1 - CSCSL: Air, groundwater, and soil (air suspected, groundwater and soil confirmed) contaminated by petroleum products (groundwater and soil only, confirmed), dioxin (suspected for all three), and polychlorinated biphenyls (PCBs)(suspected for all three); entered for all three on 3-1-88. 2 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, reported cleaned up, release status date 7-31-06. LUST #3: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #4 Groundwater contaminated, reported cleaned up, release status date 7-31-06.
243	RAINIER COURT PARCEL O	3616 34TH AVENUE S	Brownfield Listing	NR	NR	Lander and Hanford CS	No detail provided
245	RAINIER COURT PHASE II (THE DAKOTA)	3634-33RD AVE	Brownfield Listing	NR	NR	Lander and Hanford CS	No detail provided
246	DALEYS DUMP TRUCK SERVICE INC	3646 33RD S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 5-13-05. LUST #2: Soil contaminated, cleanup started, release status date 5-11-2005.
247	MCE TECHNOLOGIES INC	3670 E MARGINAL WAY S	VCP, CSCSL, LUST, and UST	Petroleum, arsenic, metals and Cyanide, non-priority	Soil and Groundwater	Hanford CS	CSCSL: Soil and groundwater (both confirmed) contaminated by petroleum products (confirmed), arsenic code (confirmed), EPA priority pollutants - metals and cyanide (confirmed), metals - other non-priority pollutant metals (confirmed), polychlorinated biphenyls (PCBs)(only soil, below cleanup level); both entered 10-12-07. 2 VCPs in progress
248	RAINIER COURT ASSOCIATES 2002-1 LLC	3700 RAINIER AVE S	CSCSL and UST	NR	NR	Lander and Hanford CS	No detail provided
249	LOCKE, 'FLUOROCARBON CO, 'SAINT GOBAIN PERFORMANCE PLASTICS	3711 S HUDSON	FIFRA / TSCA Tracking System, ICR, CSCSL (NFA), VCP, and HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 1-14-03) both listed, NFA Type: NFA after assessment, IRAP, or VCP, no further information given
250	RAINIER PLAZA SEATTLE	3800 RAINIER AVE S	ICR and CSCSL	Petroleum, non-halogenated solvents, halogenated organic compounds and metals	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL: Groundwater and soil (confirmed) contaminated by petroleum products (confirmed), non-halogenated solvents (confirmed), halogenated organic compounds (suspected), and EPA priority pollutants - metals and cyanide (suspected); both entered 4-28-94. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, final cleanup report received 1-22-96. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-12-93. ICR #3: Soil contaminated by petroleum products, final cleanup report received 3-18-94. ICR #4: Soil contaminated by petroleum products, interim cleanup report received 3-18-94. ICR #5: Soil contaminated by petroleum products, final cleanup report received 12-5-94.
251	3801 E MARGINAL WAY S, 'ASH GROVE CEMENT COMPANY, 'ASH GROVE CEMENT WEST INC	3801 E MARGINAL WAY S	FIFRA / TSCA Tracking System, ICR, CSCSL (NFA), CERCLIS (NFA), and HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing	NR	NR	Hanford CS	CSCSL NFA (7-10-98) listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given.
252	SEATTLE CITY LIGHT 4TH AVE S	3814 4TH AVE S	ICR and CSCSL	Petroleum and metals/cyanide	Soil and Groundwater	Lander and Hanford CS	CSCSL: Soil and groundwater (both confirmed) contaminated by petroleum products (confirmed) and EPA priority pollutants - metals and cyanide (confirmed); both entered 4-2-01.
253	LONGS DRUG STORE 445, 'RAINIER VALLEY SQUARE	3820 RAINIER AVE S	CSCSL (NFA) and ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL NFA (4-2-96) listed, NFA Type: NFA after assessment, IRAP, VCP; no further information given 2 - ICR #1 Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-19-96. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-22-96. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-25-95. ICR #4: Soil contaminated by petroleum products, interim cleanup report received 6-9-94. ICR #5: Soil contaminated by petroleum products, final cleanup report received 3-14-96. ICR #6: Soil contaminated by petroleum products, final cleanup report received 1-22-96. ICR #7: Soil contaminated by petroleum products, interim cleanup report received 10-25-95. ICR #8: Soil contaminated by petroleum products, final cleanup report received 1-19-96. ICR #9: Soil contaminated by petroleum products, interim cleanup report received 6-9-94.
254	CASCADE COMMERCIAL COMPANY	3825 1ST AVE S	LUST and UST	NR	Soil	Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 4-10-00. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95.

**Table G-1  
Listed Sites**

*Note: Formatted for ledger-size printing*

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
255	RODDA PAINT 4TH AVE, 'WALTS RADIATOR & MUFFLER 4TH AVE	3838 4TH AVE S	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 4-3-95. LUST #2: Soil contaminated, reported cleaned up, release status date 7-6-95. 2 - ICR: Soil contaminated by petroleum products, final cleanup report received 4-2-95
256	RESIDENCE	3839 46TH AVE. S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, final cleanup report received 5-4-94.
258	COLORADO ST FACILITY RAINIER PETRO, 'MC TERMINALS	40 S SPOKANE ST	ICR and CSCSL	Base/acid, halogenated organic compounds and PAHs	Soil and Groundwater	Hanford CS	1 - CSCSL: Groundwater (confirmed) and soil (suspected) contaminated by base/neutral/acid organics (both suspected), halogenated organic compounds (confirmed in groundwater, suspected in soil), polynuclear aromatic hydrocarbons (PAH)(both suspected); both entered 10-24-91. 2 - ICR: Groundwater contaminated by conventional organic contaminants, interim cleanup report received 8-19-91.
259	GARFIELD HIGH SCHOOL, 'SEATTLE SCHOOL DIST 1 GARFIELD HS	400 23 AV	FIFRA / TSCA Tracking System and HIST FTTS	NR	NR	Lander and Hanford CS	No detail provided
260	UNOCAL 5473	401 RAINIER AVE S	VCP, Institutional Control Site List, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed), entered 4-7-99. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-22-98. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-19-98. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-4-99. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 9-11-98. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-28-99. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-22-00. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-1-00. ICR #8: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-2-99. ICR #9: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-29-99. ICR #10: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-28-96. ICR #11: Groundwater and soil contaminated by petroleum products, interim cleanup report received 12-18-95. ICR #12: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-18-96. ICR #13: Groundwater and soil contaminated by petroleum products, interim cleanup report received date unknown. ICR #14: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-24-92. ICR #15: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-26-93. ICR #16: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-26-95. ICR #17: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-31-92. ICR #18: Groundwater and soil contaminated by petroleum products, interim cleanup report received 11-7-96. 2 VCPs in progress. 2 - LUST #1: Groundwater contaminated, cleanup started, release status date 3-24-93. LUST #2: Groundwater contaminated, monitoring, release status date 7-19-96. LUST #3: Soil contaminated, cleanup started, release status date 3-24-93. LUST #4: Soil contaminated, monitoring, release status date 9-24-90.
261	4058 RAINIER AVE S., 'DARIGOLD, 'WESTFARM FOODS SEATTLE, 'PENSKE TRUCK LEASING CO LP	4058 RAINIER AVE S	FIFRA / TSCA Tracking System, ICR, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Groundwater contaminated, cleanup started, release status date 6-1-95. ICR #1: Soil contaminated by petroleum products, interim cleanup report received 11-2-98. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 3-27-91.
262	JERGENS PAINTING, 'TANIGUCHI PROPERTY	415 18TH AVE S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 12-30-08. LUST #2: Soil contaminated, cleanup started, release status date 5-21-95.
263	BARRETT PROPERTY	416 RAINIER AVE S	CSCSL (NFA), VCP, and ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	CSCSL NFA and VCP (both 3-24-99) both listed, NFA Type: NFA after assessment, IRAP, or VCP. ICR #1: Groundwater and soil contaminated by petroleum products, final cleanup report received 11-4-98. ICR #2: Groundwater and soil contaminated by petroleum products, report received 11-4-98. ICR #3: Groundwater and soil contaminated by petroleum products, final cleanup report received 3-23-99. ICR #4: Groundwater and soil contaminated by petroleum products, final cleanup report received 11-4-98.
264	KANE PROPERTIES LLC	4208 RAINIER AVE S	CSCSL	Halogenated Organic Compounds	Soil and Suspected Groundwater	Lander and Hanford CS	CSCSL: Soil (confirmed) and groundwater (suspected) contaminated by halogenated organic compounds (confirmed for soil, suspected for groundwater), both entered 5-16-01.
270	44 SOUTH HANFORD	44 SOUTH HANFORD	HMRS	See Detailed Excerpts	NR	Hanford CS	1 - HMIRS: 30 gallons of methanol reported spilled on 6-21-01. 2 - HMIRS: 250 pounds of aluminum smelt by-product reported spilled on 3-26-03. 3 - HMIRS: .125 gallons of denatured alcohol reported spilled on 2-14-95. 4 - HMIRS: 2 gallons of methanol reported spilled on 7-6-01. 5 - HMIRS: Crude sulfate turpen vapor reported 7-14-02. 6 - HMIRS: 100 pounds of aluminum smelt by-product reported spilled on 3-26-03.
271	HARBORVIEW MENTAL HEALTH SERVICES	440 9TH AVENUE	PCB Activity Database	NR	NR	Lander and Hanford CS	No detail provided
272	JIMS AUTO REPAIR	4434 RAINIER AVE S	CSCSL, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, reported cleaned up, release status date 7-13-05. LUST #2: Soil contaminated, cleanup started, release status date 6-19-00. 2 - CSCSL: Soil (confirmed) contaminated by petroleum products (confirmed), entered on 7-13-05.

**Table G-1  
Listed Sites**

*Note: Formatted for ledger-size printing*

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
273	USVA MEDICAL CTR	4435 BEACON AVE S	FIFRA / TSCA Tracking System and HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing	NR	NR	Lander and Hanford CS	No detail provided
274	NELSON IRON WORKS, 'IRISH FOUNDRY	45 S SPOKANE ST	CSCSL (NFA), Brownfields Listing (2), and ICR	Petroleum	Soil and Groundwater	Hanford CS	CSCSL NFA and VCP (both 3-19-04) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-10-94. ICR #2: Soil contaminated by petroleum products, interim cleanup report received 9-23-91.
275	WA DOT SEATTLE S SPOKANE ST, 'WSDOT - SPOKANE ST. MAINTENANCE	450 S SPOKANE ST	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95. 2 - ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-18-94
277	SEATTLE HOUSING AUTHORITY MLK WY	4561 MARTIN LUTHER KING JR WY S	Brownfields Site List and CSCSL	Petroleum, non-halogenated solvents, and halogenated	Surface water and Groundwater	Lander and Hanford CS	CSCSL: Surface water and groundwater (both confirmed) contaminated by petroleum products (both confirmed), non-halogenated solvents (both confirmed), and halogenated organic compounds (confirmed in surface water, suspected in groundwater); both entered 6-5-07.
279	CLAYTON VW REPAIR	4709 MARTIN LUTHER KING JR WAY S	VCP, CSCSL, LUST, and UST	Petroleum, Arsenic, and PAH(s)	Soil, Groundwater, and Suspected Air and Surface Water	Lander and Hanford CS	1 - 3 VCPs in progress 2 - CSCSL: Soil (confirmed) contaminated by petroleum products (confirmed), arsenic code (confirmed), and polynuclear aromatic hydrocarbons (PAH)(confirmed); Surface water and air (both suspected) contaminated by petroleum products (suspected); all three entered on 3-5-91. 3 - LUST #1: Groundwater contaminated, cleanup started, release status date 5-21-95. LUST #2: Soil contaminated, cleanup started, release status date 5-21-95.
280	RESIDENTIAL UST	4729 51ST AVE. S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, final cleanup report received 3-23-94
284	SEATTLE CITY LIGHT SOUTH SUBSTATION	4TH AVE. S. / SPOKANE ST.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR #1: Soil contaminated by petroleum products, interim cleanup report received 8-3-90. ICR #2: Soil contaminated by total petroleum hydrocarbons, interim cleanup report received date unknown. ICR #3: Soil contaminated by petroleum products, report received 5-7-90.
285	500 17TH, 'SWEDISH MEDICAL CENTER PROVIDENCE CAMPUS, 'HOPE HEART INSTITUTE THE	500 17TH AVE RM (475D)	CSCSL (NFA), VCP, ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, reported cleaned up, release status date 4-5-00. 2 - CSCSL NFA (5-22-06) and VCP (5-22-06) both listed, no further information given 3 - ICR: Soil contaminated by petroleum products, final cleanup report received 12-30-99
287	5201 RAINIER LLC	5201 RAINIER AVE S	CSCSL (NFA)	NR	NR	Lander and Hanford CS	CSCSL NFA (3-21-08) listed, NFA Type: NFA after assessment, IRAP, or VCP
289	DAMASCUS BAPTIST CHURCH	5237 RAINIER AVE S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST: Soil contaminated, cleanup started, release status date 10-27-93.
292	DAMASCUS BAPTIST CHURCH	5261 RAINIER AVE. S.	ICR	Petroleum	Soil	Lander and Hanford CS	ICR: Soil contaminated by petroleum products, interim cleanup report received 12-10-93.
294	MOSS G MILAN PROPERTY	537 W SPOKANE ST	VCP and CSCSL	metals and Cyanide	Groundwater	Lander and Hanford CS	1 - 1 VCP in progress 2 - CSCSL: Groundwater (confirmed) contaminated by EPA priority pollutants - metals and cyanide (confirmed), entered on 12-20-05
295	MILLER RESIDENCE	5502 S FERDINAND ST	CSCSL (NFA), VCP, LUST, and UST	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 3-20-02) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given
296	RUDY HANSON, 'RUDYS SHELL SERVICE	5520 RAINIER AVE S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST: Soil contaminated, cleanup started, release status date 9-27-99
297	SEATTLE UNIVERSITY AKA BLUE WHALE, 'BLUE WHALE/SEATTLE UNIVERSITY	610 13TH AVE	ICR, LUST, and UST	Petroleum	Soil	Lander and Hanford CS	1 - LUST #1: Soil affected, reported cleaned up, release status date 8-21-91. LUST #2: Soil affected, cleanup started, release status date 6-26-91. 2 - ICR #1: Soil affected by petroleum products, final cleanup report received 8-12-91. ICR #2: Soil affected by petroleum products, interim cleanup report received 8-21-91.
298	METAL LAUNDRY INCORPORATED	614 12TH	VCP, CERCLIS (NFA), and CSCSL	Non-halogenated, halogenated organics and metals/cyanide	Soil and Groundwater	Lander and Hanford CS	CSCSL: Groundwater (confirmed) contaminated by non-halogenated solvents (confirmed), halogenated organic compounds (confirmed), and EPA priority pollutants - metals and cyanides (suspected), entered 3-1-88. Soil (confirmed) contaminated by petroleum products (confirmed), non-halogenated solvents (confirmed), and EPA priority pollutants - metals and cyanides (confirmed), entered on 3-1-88. 2 VCPs in progress.
299	TAYLOR EDWARDS SEATTLE	615 HOLGATE ST	ICR	Petroleum	Soil	Lander and Hanford CS, Lander West SB	ICR: Soil contaminated by petroleum products, final cleanup report received 8-10-90
300	ALASKAN COPPER & BRASS CO	628 S HANFORD	FIFRA / TSCA Tracking System	NR	NR	Lander and Hanford CS, Lander West SB	No detail provided
301	SOUTHERN ALASKA FORWARDERS	646 S HOLGATE ST	CSCSL (NFA), VCP, and UST	NR	NR	Lander and Hanford CS, Lander West SB	CSCSL NFA and VCP (both 2-23-09) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given
302	PAPER FIBERS RECYCLING CO, 'RABANCO RECYCLING HIGH GRADE	66 S HANFORD	FIFRA / TSCA Tracking System and HIST FTTS	NR	NR	Lander and Hanford CS	No detail provided
303	ARCO 5445, 'BP ARCO AM/PM	665 23RD AVE	LUST and UST	NR	Soil and Groundwater	Lander and Hanford CS	LUST #1: Ground water contaminated , awaiting cleanup, release status date 9-7-05. LUST #2: Soil contaminated, awaiting cleanup, release status date 9-7-05.

**Table G-1  
Listed Sites**

*Note: Formatted for ledger-size printing*

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
305	SHELL STATION 121499, 'SHELL #47481/TEXACO #121499	700 12TH AVE	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL: Groundwater and soil (both confirmed) affected by petroleum products (confirmed), entered 12-23-08 2 - ICR: Groundwater and soil affected by petroleum products, interim report received 10-4-99. 3 - ICR: Groundwater and soil affected by petroleum products, interim report received 5-15-92 4 - ICR: Groundwater affected by petroleum products, interim report received 7-11-94. 5 - ICR: Groundwater and soil affected by petroleum products, interim report received 10-16-95. 6 - ICR: Groundwater and soil affected by petroleum products, interim report (Monitoring - August 2000) received 11-8-00 7 - ICR: Groundwater and soil affected by petroleum products, interim report (Semiannual Monitoring - January 2001) received 4-25-01. 8 - ICR: Groundwater and soil affected by petroleum products, interim report (Sampling July 2001) received 12-4-01. 9 - ICR: Groundwater and soil affected by petroleum products, interim report received 5-28-93. 10 - ICR: Groundwater and soil affected by petroleum products, interim report received 12-6-93. 11 - ICR: Groundwater affected by petroleum products, interim report received 10-20-94. 12 - ICR: Groundwater affected by petroleum products, interim report received 4-5-95. 13 - ICR: Groundwater affected by petroleum products, interim report received 5-9-95. 14 - ICR: Groundwater affected by petroleum products, interim report received 5-20-95. 15 - ICR: Groundwater and soil affected by petroleum products, interim report received 4-22-97. 16 - ICR: Groundwater and soil affected by petroleum products, interim report (First Quarter Ground Water Monitoring 2002) received 6-21-02. 17 - ICR: Groundwater and soil affected by petroleum products, interim report received 4-2-98. 18 - ICR: Groundwater and soil affected by petroleum products, interim report received 5-26-00. 19 - ICR: Groundwater affected by petroleum products, interim report received 11-6-91. 20 - ICR: Groundwater affected by petroleum products, interim report received 12-1-92. 21 - LUST #1: Groundwater affected, monitoring, release status date 10-1-95. LUST #2: Soil affected, monitoring, release status date 10-1-95. LUST #3: Soil affected, monitoring, release status date 4-18-97. LUST #4: Soil affected, cleanup started, release status date 12-27-90. LUST #5: Groundwater affected, monitoring, release status date 4-18-97. LUST #6: Groundwater affected, cleanup started, release status date 12-27-90.
306	CITY OF SEATTLE, 'SEATTLE CITY HEALTH DEPT, 'CHARLES STREET SITE WEST	705 CHARLES ST. E.	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	LUST #1: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95. ICR #1: Soil contaminated by petroleum products, interim cleanup report (Final - UST Removal and Soil/GW Investigation) received 6-29-93. ICR #2: Soil contaminated by petroleum products, interim cleanup report (Appendices - UST Removal and Soil/GW Investigation) received 6-29-93.
309	TEXACO #63232 1489	719 RAINIER AVE. S.	ICR	Petroleum	Groundwater	Lander and Hanford CS	ICR: Groundwater contaminated by petroleum products, interim cleanup report received 5-22-95.
310	GRAY LINE OF SEATTLE	720 S FOREST ST	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	LUST #1: Soil contaminated, cleanup started, release status date 9-28-95. LUST #2: Groundwater contaminated, cleanup started, release status date 9-28-95. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-14-90. ICR #2: Groundwater and soil contaminated, final cleanup report received 4-11-91.
311	UNK, '12TH & COLUMBIA SITE	729 12TH AVE	CSCSL (NFA) and VCP	NR	NR	Lander and Hanford CS	CSCSL NFA (8-8-02) and VCP (8-8-02) listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given.
312	SWEDISH HOSPITAL MEDICAL CTR	747 BROADWAY	LUST and UST	Soil	NR	Lander and Hanford CS	LUST #1: Soil contaminated, cleanup started, release status date 2-23-93. LUST #2: Soil contaminated, reported cleaned up, release status date 6-1-95. LUST #3: Soil contaminated, cleanup started, release status date 12-24-91. LUST #4: Soil contaminated, reported cleaned up, release status date 6-1-95.
314	SEARS ROEBUCK & CO 1009	76 S LANDER ST	FIFRA / TSCA Tracking System, HIST FTTS FIFRA/TSCA Tracking System Administrative Case Listing, CSCSL, LUST and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed); both entered 3-15-07. LUST #1: Soil contaminated, awaiting cleanup, release status date 6-1-95. LUST #2: Groundwater contaminated, awaiting cleanup, release status date 6-1-95.
315	MARKEY MACHINERY CO INC	79 S HORTON ST	CSCSL (NFA) and VCP	NR	NR	Hanford CS	CSCSL NFA and VCP (both 1-22-08) both listed, NFA Type: NFA after assessment, IRAP, or VCP; no further information given
317	FOOD SERVICE INTERNATIONAL	801 S HOLGATE	ICR, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 11-20-91. LUST #2: Soil contaminated, reported cleaned up, release status date 6-1-95. 2 - ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 3-13-92. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-13-93.

**Table G-1  
Listed Sites**

*Note: Formatted for ledger-size printing*

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
319	MODEL & INSTRUMENT DEVELOPMENT, 'SIGNAL EQUIPMENT INC.	836 POPLAR PL S	CERCLIS (NFA), ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - ICR #1: Soil contaminated by petroleum products, final cleanup report received 5-22-94. ICR #2: Soil contaminated by petroleum products, final cleanup report received 9-11-92. 2 - ICR: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-10-92. 3 - CSCSL: Soil (confirmed) and groundwater (suspected) contaminated by petroleum products (confirmed in soil, suspected in groundwater), both entered 8-1-05. 4 - LUST #1: Groundwater contaminated, cleanup started, release status date 6-1-95. LUST #2: Soil contaminated, cleanup started, release status date 6-1-95.
321	THE RECYCLING DEPOT INC	851 RAINIER AVE S	Solid Waste Facility Database	NR	NR	Lander and Hanford CS	No detail provided
322	SHELL RAINIER AVE S SEATTLE, 'SHELL STATION 121607	852 RAINIER AVE S	VCP, ICR, CSCSL, LUST, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - LUST #1: Soil contaminated, cleanup started, release status date 4-11-91. LUST #2: Groundwater contaminated, monitoring, release status date 9-8-94. LUST #3: Groundwater contaminated, cleanup started, release status date 4-11-91. LUST #4: Soil contaminated, monitoring, release status date 9-8-94. 2 - 2 VCPs in progress 3 - CSCSL: Groundwater and soil (both confirmed) contaminated by petroleum products (confirmed for both) and metals - other non-priority pollutant metals (confirmed for groundwater, below cleanup level for soil), both entered 2-17-09. ICR #1: Groundwater and soil contaminated by petroleum products, interim cleanup report received 1-30-98. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 7-31-98. ICR #3: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-27-98. ICR #4: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-11-99. ICR #5: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-6-99. ICR #6: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-26-00. ICR #7: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-15-91. ICR #8: Groundwater and soil contaminated by petroleum products, interim cleanup report received date unknown. ICR #9: Groundwater and soil contaminated by petroleum products, interim cleanup report received 11-24-93. ICR #10: Groundwater and soil contaminated by petroleum products, interim cleanup report received 2-20-95. ICR #11: Groundwater contaminated by petroleum products, interim cleanup report received 4-24-95. ICR #12: Groundwater and soil contaminated by petroleum products, interim cleanup report received 5-30-95. ICR #13: Groundwater and soil contaminated by petroleum products, interim cleanup report received 10-16-95. ICR #14: Groundwater and soil contaminated by petroleum products, interim cleanup report (Monitoring - January 2001) received 3-20-01. ICR #15: Groundwater contaminated by petroleum products, interim cleanup report received 1-17-96. ICR #16: Groundwater and soil contaminated by petroleum products, interim cleanup report received 8-23-96. ICR #17: Groundwater and soil contaminated by petroleum products, interim cleanup report (Sampling - August 2001) received 12-4-01. ICR #18: Groundwater and soil contaminated by petroleum products, interim cleanup report (Monitoring - September 2000) received 11-13-00. ICR #19: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-16-96. ICR #20: Groundwater and soil contaminated by petroleum products, interim cleanup report received 4-21-97. ICR #21: Groundwater and soil contaminated by petroleum products, interim cleanup report (Fourth Quarter Ground Water Monitoring 2002) received 12-11-02. ICR #22: Groundwater and soil contaminated by petroleum products, interim cleanup report (Ground Water Monitoring - March 2002) received 6-21-02.
323	EMERALD CITY DISPOSAL MASSACHUSETTS, 'COAL CREEK DEVELOPMENT LANDFILL, 'US COAST GUARD PIER 35	9 S MASSACHUSETTS	ICP, CSCSL, LUST, and UST	Petroleum and halogenated organic compounds,	Surface water and Soil	B-25 SB	1 - CSCSL: Surface water (confirmed) contaminated by petroleum products (below cleanup level) and halogenated organic compounds (confirmed); soil (confirmed) contaminated by petroleum products (confirmed) and halogenated organic compounds (below cleanup level); both entered 11-9-04 2 - LUST: Soil contaminated, cleanup started, release status date 10-5-98 3 - ICR: Soil contaminated by petroleum products, interim cleanup report received 10-7-08.
324	'CANELLA INC	'901 HIAWATHA PL S	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 1-2-08. LUST #2: Soil contaminated, cleanup started, release status date 12-21-07.
326	HOSPITAL CORP OF AMERICA 904, 'SHEPARD AMBULANCE	904 12TH AVE	CSCSL (NFA), ICR, and UST	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL NFA dated 12-1-95, but no further information given. 2 - ICR #1: Soil contaminated by petroleum products, final cleanup report received 8-7-95. ICR #2: Groundwater and soil contaminated by petroleum products, interim cleanup report received 6-2-94.
327	MOTOR FREIGHT SERVICES INC	916 COLLEGE ST	CSCSL, VCP, and ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS, Lander West SB	1 - CSCSL NFA and VCP (both 5-14-99) both listed, NFA Type: NFA after assessment, IRAP, or VCP 2 - ICR #1: Groundwater and soil contaminated by petroleum products and halogenated solvents, interim cleanup report received 7-15-98. ICR #2: Groundwater and soil contaminated by halogenated organic compounds and petroleum products, final cleanup report received 4-22-99.
329	MOSS ALLEY MOTORS	932 12TH AVE	CSCSL (NFA) and ICR	Petroleum	Soil and Groundwater	Lander and Hanford CS	1 - CSCSL NFA (12-1-95) listed, no further information given 2 - Groundwater and soil contaminated by petroleum products, final cleanup report received 8-7-95
331	SEATTLE UNIVERSITY	BROADWAY & E MADISON	FIFRA / TSCA Tracking System, ICR, and HIST	Petroleum	Soil and Groundwater	Lander and Hanford CS	ICR #1: Groundwater and soil contaminated by petroleum products, final cleanup report received 10-5-98. ICR #2: Soil contaminated by petroleum products, final cleanup report received 5-21-93.

**Table G-1  
Listed Sites**

*Note: Formatted for ledger-size printing*

Map ID	Site Name	Site Address	Database	Reported Contaminants	Media Affected	Drainage Basin(s)	Detailed Excerpt From Report
333	GENESEE LANDFILL	GENESEE ST / 43RD AVE S	CSCSL	Pesticides, halogenated organic compounds,	Air, and Suspected Groundwater, Surface Water and Soil	Lander and Hanford CS	CSCSL: Groundwater, surface water, and soil (all suspected) contaminated by pesticides (suspected), halogenated organic compounds (suspected), EPA priority pollutants - metals and cyanide (suspected), and polynuclear aromatic hydrocarbons (PAH)(suspected); air (confirmed) contaminated by inorganic conventional contaminants; all four entered on 3-1-88.
334	SEATTLE CITY ROW HOLGATE & 3RD	HOLGATE AVE / 3RD AVE S	CSCSL	Arsenic and metals/cyanide	Soil and Suspected Groundwater	Lander and Hanford CS, Lander West SB	CSCSL: Soil (confirmed) contaminated by arsenic code (confirmed) and EPA priority pollutants - metals and cyanide (confirmed); groundwater (suspected) contaminated by arsenic code (suspected) and EPA priority pollutants - metals and cyanide (suspected); both entered 9-1-04
335	WA DOT I-90 & RAINIER AVE	I-90 / RAINIER AVE S	CSCSL (NFA) and VCP	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 5-21-95. LUST #2: Soil contaminated, cleanup started, release status date 1-25-89.
337	SWEDISH HOSPITAL GAS STATIONS	MADISON MINOR MARION BOREN	LUST and UST	NR	Soil	Lander and Hanford CS	LUST #1: Soil contaminated, reported cleaned up, release status date 5-21-91. LUST #2: Soil contaminated, cleanup started, release status date 6-26-91.
338	SEATTLE, CY OF, RAINIER PLAYFIELD	OREGON ST S & 38TH	Brownfield Listing	NR	NR	Lander and Hanford CS	No detail provided
341	RAINIER COURT	RAINIER AVE S	Brownfeild Listing, VCP, and CSCSL	Pesticides, Petroleum, metals/cyanide, PCBs, and PAHs	Soil and Groundwater	Lander and Hanford CS	1 - 2 VCPs in progress 2 - CSCSL: Groundwater and soil (both confirmed) contaminated by pesticides (below cleanup level), petroleum products (confirmed), EPA priority pollutants - metals and cyanide (confirmed), polychlorinated biphenyls (PCBs)(below cleanup level), polynuclear aromatic hydrocarbons (PAHs)(confirmed); both entered 6-19-01.
344	SEATTLE CITY ROW S HORTON & OCCIDENTAL S	S HORTON ST /	CSCSL	Petroleum	Soil	Hanford CS	CSCSL: (Soil confirmed) contaminated by petroleum products (confirmed), entered on 1-1-07.
345	WA DOT SEATTLE I90 TIME OIL	S NORMAN ST /	CSCSL (NFA) and VCP	NR	NR	Lander and Hanford CS	CSCSL NFA and VCP (both 7-19-00) both listed, NFA Type: NFA after assessment, IRAP, or VCP, no further information given

Notes:

- CS = Combined Sewer
- CSCSL = Confirmed and Suspected Contaminated Site List
- ICR = Independent Cleanup Report
- LUST = Leaking Underground Storage Tank Database
- NFA = No Further Action
- NR = Not Reported
- SB = Stormwater Basin
- UST = Underground Storage Tank Database
- VCP = Voluntary Cleanup Program

All sites were listed on one or more of the following databases: Corrective Action Report, FIFRA / TSCA Tracking System, CSCSL - No Further Action, Brownfields Site List, Voluntary Site Cleanup Program Sites, PCB Activity Database, Institutional Control Site List, a listing of brownfield sites, CERCLIS, CERCLIS (no further action), Independent Cleanup Reports, Hazardous Material Reporting System, EDR Proprietary Manufactured Gas Plants, ICIS Integrated Compliance Information System, HIST FTTS FIFRA / TSCA Tracking System Administrative Case Listing, Confirmed and Suspected Contaminated List, Leaking Underground Storage Tank, Solid Waste Facility Database, Material Licensing Tracking System, Hazardous Sites List, Underground Storage Tank Database, RCRA Administrative Action Tracking System